

## Panel .40

Panel .41 Panel .42

Panel .46

Panel .47

Panel .48

Panel .59

- Panel .55/57

- Panel .53/54

- Panel .56/58

Panel .62

- Panel .64/66

Panel .81

Panel .80

- Panel .79

Panel .75


Panel .74

Panel .73

- Panel .63/65


Panel .07 Panel .01	
Panel .14 Panel .08 Panel .02	
Panel .15 Panel .09 Panel .03	
Panel .16 Panel .10 Panel .04	
Panel .17 Panel .11 Panel .05	
Panel .12 Panel .06	
















1:200

	All dimensions to be site checked and Captu to be nofied of any discrepancies prior to t work. All materials and workmanship to relevant i pracce and manufacturers ecommendao Use annotated dimensions in all cases. This drawing is copyright and should not be part without wrien consent of Capture Int DO NOT SCALE FROM THIS DRAWI	the commencement of Brish Standards codes of ns . reproduced in whole or erior Architecture Ltd.
—— Panel .24 —— Panel .18		— Panel .31
Panel .19 Panel .13 Panel .25		— Panel .32
—— Panel .26 —— Panel .20		— Panel .33
—— Panel .27 —— Panel .21		— Panel .34
— Panel .28 — Panel .22		— Panel .35
—— Panel .29 —— Panel .23		— Panel .30 — Panel .36
KEY   4 Panels in total   - Transverse rib   - Full panel of lath and plaster to be reinstate   - Plaster to be reinstated on existing lath wor	■ interior architecture	hedley design

- Damage present to ribs of roof structure

Ponteland Newcastle Upon Tyne NE20 9SD 01661 822017 info@captureia.co.uk info@hedleydesign.co.uk Job Title: St Andrew's Church & Centre Church Street, Hebburn Client: DMCN Drawing Name: Existing Ceiling Photographs

Drawing Number: C039(B)11

Scale: 1:200, 1:100

Date: 02/07/2015

