

0401 - External Window Schedule 1 Beach Road, Building 1					
Mark	Width	Height	Sill Height	Head Height	Comments
B1.BL.W01	1425	1575	1355	2930	To be Replaced to Match Existing. To be security sash window. Bars to be removed and security locks installed.
B1.BL.W02	1425	1575	1355	2930	To be Replaced to Match Existing. To be security sash window. Bars to be removed and security locks installed.
B1.BL.W03	1275	1975	910	2885	To be Replaced to Match Existing. To be security sash window. Bars to be removed and security locks installed.
B1.BL.W04	545	675	2140	2815	To be repainted. Lintel to be review by Structural Engineer.
B1.FL.W01	1425	2050	650	2700	To be Repaired by Specialist Sub-Contractor as required.
B1.FL.W02	1425	2050	650	2700	To be Repaired by Specialist Sub-Contractor as required.
B1.FL.W03	1425	2050	650	2700	To be Repaired by Specialist Sub-Contractor as required.
B1.FL.W04	1425	2050	650	2700	To be Repaired by Specialist Sub-Contractor as required.
B1.FL.W05	1425	2050	650	2700	To be Repaired by Specialist Sub-Contractor as required.
B1.FL.W06	675	1450	800	2250	To be Repaired by Specialist Sub-Contractor as required.
B1.FL.W07	550	600	545.05	1145.05	To be Repaired by Specialist Sub-Contractor as required.
B1.FL.W08	1275	1975	660	2635	To be Repaired by Specialist Sub-Contractor as required.
B1.GF.W103	630	1035	805.58	1840.58	Coach House to be Demolished
B1.GF.W104	1190	1175	981.04	2156.04	Coach House to be Demolished
B1.GF.W105	400	600	1525	2125	Coach House to be Demolished
B1.GL.W01	1425	2110	655	2765	To be Repaired by Specialist Sub-Contractor as required.
B1.GL.W02	1425	2110	655	2765	To be Repaired by Specialist Sub-Contractor as required.
B1.GL.W03	1425	2110	655	2765	To be Repaired by Specialist Sub-Contractor as required.
B1.GL.W04	1425	2110	655	2765	To be Repaired by Specialist Sub-Contractor as required.
B1.GL.W05	1275	2025	2035	4060	To be Repaired by Specialist Sub-Contractor as required.
B1.GL.W06	1275	2025	660	2685	To be Repaired by Specialist Sub-Contractor as required.
B1.GL.W07	575	1525	880	2405	To be Repaired by Specialist Sub-Contractor as required.
B1.SF.RL01	615	875			To be replaced with conservation rooflight smoke vent likely required to stair.
B1.SF.RL02	615	875			To be replaced with conservation rooflight.
B1.SF.W01	1200	1055	1010	2065	To be Repaired by Specialist Sub-Contractor
B1.SF.W02	1200	1055	990	2045	To be Repaired by Specialist Sub-Contractor

0402 - External Window Schedule 3 and 3a Beach Road, Building 2					
Mark	Width	Height	Sill Height	Head Height	Comments
B2.BL.W01	1245	1575			To be Repaired by Specialist Sub-Contractor. Bars to be removed and security restrictors to be installed.
B2.BL.W02	1245	1925	975	2900	Modern replacement. To be security sash window. Bars to be removed and security locks installed.
B2.BL.W03	1050	1750	1125	2875	To be Repaired by Specialist Sub-Contractor. Bars to be removed and security restrictors to be installed.
B2.BL.W04	1050	1750	1125	2875	To be Repaired by Specialist Sub-Contractor. Bars to be removed and security restrictors to be installed.
B2.BL.W05	1050	1750	1125	2875	To be Repaired by Specialist Sub-Contractor. Bars to be removed and security restrictors to be installed.
B2.BL.W06	1325	1175	1565	2740	New uPVC window. Modern alteration by previous owner - to remain.Bars to be removed security restrictors to be installed.
B2.FL.W01	1000	2000	700	2700	To be Repaired by Specialist Sub-Contractor
B2.FL.W02	1275	2000	700	2700	To be Repaired by Specialist Sub-Contractor
B2.FL.W03	1245	1925	735	2660	To be Repaired by Specialist Sub-Contractor as required.
B2.FL.W04	500	625	1268.19	1893.19	To be Repaired by Specialist Sub-Contractor as required.
B2.FL.W05	550	750	750	1500	To be Repaired by Specialist Sub-Contractor as required.
B2.FL.W06	675	1375	370	1745	To be Repaired by Specialist Sub-Contractor, Bars to be removed.
B2.FL.W07	675	1375	370	1745	To be Repaired by Specialist Sub-Contractor
B2.FL.W08	665	1110	655	1765	To be Repaired by Specialist Sub-Contractor, Bars to be removed.
B2.G.i01	1500	850	1770	2620	Internal Screen to be filled in
B2.G.i02	675	625	2245	2870	Internal Screen to be filled in
B2.GL.W01					To be Repaired by Specialist Sub-Contractor
B2.GL.W02					To be Repaired by Specialist Sub-Contractor
B2.GL.W03	1175	1875	840	2715	To be Repaired by Specialist Sub-Contractor as required. Bars to be removed and security restrictors to be installed
B2.SF.W01	940	925	1035	1960	To be Replaced to Match Existing
B2.SF.W02	940	925	1065	1990	To be Repaired by Specialist Sub-Contractor

TO BE READ IN CONJUNCTION WITH WINDOW SCHEDULE PHOTOGRAPHIC RECORD.

- Prepared from visual inspection. Inspection is to be carried out by specialist to determine limits to repair.
- Subject to review by window repair specialist and structural engineer where noted.
- Draft proofing to be reviewed with repair specialist.
- Any new windows with a cill below 800mm to be toughened and laminated in accordance with approved Doc N.
- All repaired windows to be refinished. Precautions should be made presence of lead paint.

©Edwards Architecture Ltd.

1. Do not scale off this drawing. Use figured dimensions only

2. All dimensions are in millimeters unless otherwise noted

3. All dimensions to be checked on site.

4. All omissions & discrepancies to be reported to the architect immediately

5. Check site conditions prior to commencement of works

6. This drawings is to be read in conjunction with other consultants & specialists drawings

R e v	Description	Date
P0	1 First Issue	07.02.21

4 Vila House, Fish Quay, North Shields. NE30 1JA

T: 0191 649 8404

E: info@edwardsarchitecture.co.uk

W: www.edwardsarchitecture.co.uk

Project

20063 - Beach Road, South Shields

Mandeville Properties

Drawing Title

Window Schedule 1 3 & 3a Beach Road

Scale at A3

Information Issued

Stage/ Level/

Project

Originator

Volume

Locat.

Type

Role

Number

Rev

20063 - EArch - CN - XX - SC - A - 0401 - P01