


Jarrow Town Hall – Photo Schedule



JTH View Mark up 2

- Pink = balustrade / parapet wall with gutter behind
- Green = Small Arch with Parapet behind
- Blue = Parapet wall with failed render
- Yellow = Tower with patched render repair
- Purple = Gable end with patch render repairs



JTH View Mark up 1

- Pink = balustrade / parapet wall with gutter behind
- Green = Small Arch with Parapet behind
- Blue = Parapet wall with failed render
- Yellow = Tower with patched render repair
- Purple = Gable end with patch render repairs



Front Elevation, Parapet wall, with loose capping stones and vegetation in joints



Parapet wall with failed render, loose capping stones and vegetation



Side Elevation, Gable end wall with partial render repair to brick



Side Elevation, behind small arch / parapet wall.
Debris blocking out to rainwater goods



Debris blocking outlet to rainwater good, causing water ingress into building



Blocked gutter causing water ingress into building



Balustrade / parapet wall with vegetation to joints and blocked gutter



Small decorative arch with vegetation to joints and failed netting



20260128_081427



20260128_081436



Blocked gutter behind balustrade / parapet wall



Joints with vegetation and ineffective water diversion inside small arch. Later addition.
Also note failed netting



Failed Render to small parapet wall behind small arch. Also note vegetation to joints.



Front elevation



Small Arch from front



Small Arch from the front



Side elevation view of rendered wall



Side elevation, capping to parapet wall, showing failed render



Chimney with failed haunching



Side elevation with patched failed render and vegetation



View from rear of small arch, showing vegetation growth in all the failed joints



Gable end showing vegetation to failed render



View from above small arch



View from above small arch and parapet wall



Small arch from above



Small arch / gable wall capping



Main Tower with patch render repairs, failed / damaged brick work and vegetation growth to joints



Small arch / chimney / gable wall



Gable wall facing to rear, showing 2nd chimney stack



Gable end with vegetation growth and failed render /
damaged brick work



View from side gable to rear of site



View of Ach to front of site



Small Parapet wall showing loose capping and failed render



Gable End wall



Small Parapet wall showing loose capping and failed render



Small Parapet wall showing loose capping and failed render



Front Elevation – vegetation growth and gaps to joints



Side View above small arch / chimney stack