South Tyneside Council

Specific Areas of Leisure Centre
Temple Park Leisure Centre
John Reid Road, South Shields, NE34 9UG

Project Number:	B-66870
Survey Date:	04/11/2011
Client Contact:	Michael Hicks South Tyneside Council
Address:	Town Hall, Civic Offices Westoe Road South Shields Tyne and Wear NE33 2RL
Tel:	0191 424 7239

This Asbestos Survey Report has been authorised by the relevant Project Surveyor.

Name: **Chris Oyston**

Signature: [redacted]

Date: 09/01/2012

UKAS INSPECTION
146

The OHS 360° Principle | The Knowledge Chain | The Learning Curve

ASR010-12a

CONTENTS

1.0 Executive Summary

2.0 Introduction, Scope of Service

3.0 General Site and Survey Information

4.0 Asbestos Register (including Material Assessments)

5.0 Non Asbestos Register

6.0 Conclusions and Actions

7.0 Bulk Sample Analysis

8.0 Site Plan

9.0 Pre-Survey Questionnaire / Survey Scope

1.0 EXECUTIVE SUMMARY

This report is a 1.2 Demolition Survey of those areas of the premises instructed by the Client and identified on the plan enclosed in the report.

Detailed below are the Asbestos Containing Materials (ACM's) including presumed ACM's identified together with a 'risk' allocated by the surveyor at the time of the inspection based upon the material assessment.

High Risk **Material Assessment Score ≥10**

Building	Floor	Area	Location	Material	Recommendations	Action date
No high risk materials identified within the scope of this survey.						

Medium Risk **Material Assessment Score 7-9**

Building	Floor	Area	Location	Material	Recommendations	Action date
No medium risk materials identified within the scope of this survey.						

Low Risk **Material Assessment Score 5-6**

Building	Floor	Area	Location	Material	Recommendations	Action date
Temple Park Leisure Centre	2	001	Tank Room	Gaskets - Asbestos Textiles	Remove all asbestos materials, prior to refurbishment, should the materials not be removed within the 3 month period stated within HSG264, the information collated will be required to assist in the compilation of a management survey	Prior to refurbishment
Temple Park Leisure Centre	0	011	Plant Room	Gaskets - Asbestos Textiles	Remove all asbestos materials, prior to refurbishment, should the materials not be removed within the 3 month period stated within HSG264, the information collated will be required to assist in the compilation of a management survey	Prior to refurbishment
Temple Park Leisure Centre	0	011	Plant Room	Gaskets - Asbestos Textiles	Remove all asbestos materials, prior to refurbishment, should the materials not be removed within the 3 month period stated within HSG264, the information collated will be required to assist in the compilation of a management survey	Prior to refurbishment

Very Low Risk **Material Assessment Score ≤4**

Building	Floor	Area	Location	Material	Recommendations	Action date
Temple Park Leisure Centre	0	094	Cellar	Sink Pad - Bitumen/Felts	Remove all asbestos materials, prior to refurbishment, should the materials not be removed within the 3 month period stated within HSG264, the information collated will be required to assist in the compilation of a management survey	Prior to refurbishment

No Access

Building	Floor	Area	Location	Material	Reason for No Access
Temple Park Leisure Centre	0	100	Lift Shaft	No Access - Unknown	Lift engineer required.

Until such time as limited/no access areas can be inspected and any suspect materials contained within have been sampled and analysed by a competent person, in accordance with HSG264, these areas should be presumed to contain asbestos

2.0 INTRODUCTION, SCOPE OF SERVICE

2.1 OHS Ltd were instructed to provide a 1.2 Demolition Survey of Temple Park Leisure Centre. The object and purpose of the survey was to identify where as far as reasonably practical ACM's within the scope of the instructions received.

2.2 Where a project specific/intrusive survey is undertaken, it is important that the marked up plans are read in conjunction with the full report.

2.3 OHS Ltd requested details of the following ahead of the survey

- Details of the buildings or parts of buildings to be surveyed and survey type(s).
- Details of the building(s) use, age, size, processes, hazards and priority areas.
- Plans, documents, reports and surveys on design, structure and construction.
- Safety and security information, fire alarm testing, special clothing areas.
- Access arrangements and permits.
- Contracts for operational or health and safety issues.

2.4 This Asbestos Survey Report must be read in conjunction with OHS Ltd Asbestos Surveying and Methodology (Ref: ASR001). The OHS Ltd Terms and Conditions are available on our website www.ohs.co.uk.

2.5 It should be noted that the Asbestos Survey Report is not intended to be used as a Bill of Quantities for the removal of asbestos containing materials (ACMs) identified at the site and should be used as a reference document only when tendering. All quantities detailed within the Asbestos Survey Report are approximations and should be verified by a competent person.

2.6 This survey forms only part of the Duty to Manage Asbestos (Reg 4 Control of Asbestos Regulations 2006). Compliance can be achieved by following the OHS Knowledge Chain™

2.7 This report is intended for the recipient named only. This report is not to be relied upon by any 3rd Party. This report must be read in its entirety and is in conjunction with the Client's order and all associated correspondence.

3.0 GENERAL SITE AND SURVEY INFORMATION

Surveying Organisation Details:

OHS Limited
Listerhills Science Park
11-17 Campus Road
Bradford
BD7 1HR

The Surveyor(s) names: Chris Oyston

Client Details:
Michael Hicks
South Tyneside Council
Town Hall, Civic Offices
Westoe Road
South Shields
Tyne and Wear
NE33 2RL

The name and address of the premises surveyed:

Temple Park Leisure Centre
John Reid Road
South Shields
NE34 9UG

The age of the premises: Pre - 1985

Approximate size of building/area: Unknown (sq ft)

Property Type: Leisure

Site Status: Operational

The date of the survey: 04/11/2011

The date of the report: 09/01/2012

Description of the areas included in the survey: Please refer to enclosed plan (section 8)

Description of areas excluded from the survey: Please refer to enclosed plan (section 8)


Survey method used: OHS ASR010 and HSG264


The Type(s) of Survey undertaken: 1.2 Demolition Survey





Any variation or deviations from the method: Please refer to non-accessed areas (section 1).


Agreed exclusions and inaccessible areas: Please refer to non-accessed areas (section 1).








4.0 ASBESTOS REGISTER (including Material Assessment)

Location/Item	Type of Survey	Product Type	Extent	Accessibility	Condition	Surface Treatment	Asbestos Type	Sample	Material Assessment Score	Photo
Floor 0 - Corridor - 010 - Mastic	Refurb-demolition	Organic	-	Difficult	Good Condition	N/A	NAD	040 (Visually Consistent)	No Asbestos Detected	
Floor 0 - Plant Room - 011 - Gaskets	Refurb-demolition	Asbestos Textiles	Throughout	Medium	Low Damage	Asbestos Textiles	Chrysotile (white)	018	6	
Floor 0 - Plant Room - 011 - Gaskets	Refurb-demolition	Asbestos Textiles	1no.	Easy	Low Damage	Asbestos Textiles	Chrysotile (white)	025	6	
Floor 0 - Plant Room - 011 - Debris	Refurb-demolition	Organic	-	Easy	Good Condition	N/A	NAD	019	No Asbestos Detected	
Floor 0 - Plant Room - 011 - Pipe Insulation	Refurb-demolition	Organic	-	Medium	Good Condition	N/A	NAD	020	No Asbestos Detected	
Floor 0 - Plant Room - 011 - Pipe Insulation	Refurb-demolition	Organic	-	Medium	Good Condition	N/A	NAD	021	No Asbestos Detected	
Floor 0 - Plant Room - 011 - Pipe Insulation	Refurb-demolition	Organic	-	Medium	Good Condition	N/A	NAD	022	No Asbestos Detected	





Location/Item	Type of Survey	Product Type	Extent	Accessibility	Condition	Surface Treatment	Asbestos Type	Sample	Material Assessment Score	Photo
Floor 0 - Plant Room - 011 - Pipe Insulation	Refurb-demolition	Organic	-	Medium	Good Condition	N/A	NAD	023	No Asbestos Detected	
Floor 0 - Plant Room - 011 - Pipe Insulation	Refurb-demolition	Organic	-	Medium	Good Condition	N/A	NAD	024	No Asbestos Detected	
Floor 0 - Stairwell - 014 - Floor Covering	Refurb-demolition	Organic	-	Easy	Good Condition	N/A	NAD	033 (Visually Consistent)	No Asbestos Detected	
Floor 0 - Stairwell - 014 - Stair Nosing	Refurb-demolition	Organic	-	Easy	Good Condition	N/A	NAD	034 (Visually Consistent)	No Asbestos Detected	
Floor 0 - Stairwell - 014 - Bulkhead	Refurb-demolition	Organic	-	Medium	Good Condition	N/A	NAD	035 (Visually Consistent)	No Asbestos Detected	
Floor 0 - Stairwell - 014 - Ceiling Tiles	Refurb-demolition	Organic	-	Medium	Good Condition	N/A	NAD	032 (Visually Consistent)	No Asbestos Detected	
Floor 0 - Store Room - 017 - Sink Pad	Refurb-demolition	Organic	-	Medium	Good Condition	N/A	NAD	001	No Asbestos Detected	




Location/Item	Type of Survey	Product Type	Extent	Accessibility	Condition	Surface Treatment	Asbestos Type	Sample	Material Assessment Score	Photo
Floor 0 - Electrical Switchroom - 023 - Panel	Refurb-demolition	Organic	-	Difficult	Good Condition	N/A	NAD	039 (Visually Consistent)	No Asbestos Detected	
Floor 0 - Corridor - 024 - Mastic	Refurb-demolition	Organic	-	Difficult	Good Condition	N/A	NAD	040 (Visually Consistent)	No Asbestos Detected	
Floor 0 - Male Wc - 026 - Ceiling Tiles	Refurb-demolition	Organic	-	Medium	Good Condition	N/A	NAD	039 (Visually Consistent)	No Asbestos Detected	
Floor 0 - Female Wc - 027 - Ceiling Tiles	Refurb-demolition	Organic	-	Medium	Good Condition	N/A	NAD	039 (Visually Consistent)	No Asbestos Detected	
Floor 0 - Changing Room - 046 - Mastic	Refurb-demolition	Organic	-	Difficult	Good Condition	N/A	NAD	040	No Asbestos Detected	
Floor 0 - Changing Room - 046 - Floor Covering	Refurb-demolition	Organic	-	Easy	Good Condition	N/A	NAD	033 (Visually Consistent)	No Asbestos Detected	
Floor 0 - Changing Room - 048 - Ceiling Tiles	Refurb-demolition	Organic	-	Medium	Good Condition	N/A	NAD	039	No Asbestos Detected	


Location/Item	Type of Survey	Product Type	Extent	Accessibility	Condition	Surface Treatment	Asbestos Type	Sample	Material Assessment Score	Photo
Floor 0 - Changing Room - 050 - Ceiling Tiles	Refurb-demolition	Organic	-	Medium	Good Condition	N/A	NAD	039 (Visually Consistent)	No Asbestos Detected	
Floor 0 - Wc - 051 - Mastic	Refurb-demolition	Organic	-	Difficult	Good Condition	N/A	NAD	040 (Visually Consistent)	No Asbestos Detected	
Floor 0 - Corridor - 053 - Mastic	Refurb-demolition	Organic	-	Difficult	Good Condition	N/A	NAD	040 (Visually Consistent)	No Asbestos Detected	
Floor 0 - Corridor - 053 - Ceiling Tiles	Refurb-demolition	Organic	-	Medium	Good Condition	N/A	NAD	039 (Visually Consistent)	No Asbestos Detected	
Floor 0 - Changing Room - 055 - Wall Panel	Refurb-demolition	Organic	-	Medium	Good Condition	N/A	NAD	039 (Visually Consistent)	No Asbestos Detected	
Floor 0 - Changing Room - 056 - Ceiling Tiles	Refurb-demolition	Organic	-	Medium	Good Condition	N/A	NAD	039 (Visually Consistent)	No Asbestos Detected	
Floor 0 - Changing Room - 057 - Mastic	Refurb-demolition	Organic	-	Difficult	Good Condition	N/A	NAD	040 (Visually Consistent)	No Asbestos Detected	




Location/Item	Type of Survey	Product Type	Extent	Accessibility	Condition	Surface Treatment	Asbestos Type	Sample	Material Assessment Score	Photo
Floor 0 - Changing Room - 079 - Ceiling Tiles	Refurb-demolition	Organic	-	Medium	Good Condition	N/A	NAD	039 (Visually Consistent)	No Asbestos Detected	
Floor 0 - Wc - 080 - Mastic	Refurb-demolition	Organic	-	Difficult	Good Condition	N/A	NAD	040 (Visually Consistent)	No Asbestos Detected	
Floor 0 - Wc Entrance Lobby - 081 - Wall Panel	Refurb-demolition	Organic	-	Medium	Good Condition	N/A	NAD	039 (Visually Consistent)	No Asbestos Detected	
Floor 0 - Office - 083 - Ceiling Tiles	Refurb-demolition	Organic	-	Medium	Good Condition	N/A	NAD	039 (Visually Consistent)	No Asbestos Detected	
Floor 0 - Office - 083 - Floor Covering	Refurb-demolition	Organic	-	Easy	Good Condition	N/A	NAD	042	No Asbestos Detected	
Floor 0 - Changing Room - 085 - Ceiling Tiles	Refurb-demolition	Organic	-	Medium	Good Condition	N/A	NAD	039 (Visually Consistent)	No Asbestos Detected	
Floor 0 - Changing Room - 087 - Ceiling Tiles	Refurb-demolition	Organic	-	Difficult	Good Condition	N/A	NAD	039 (Visually Consistent)	No Asbestos Detected	


Location/Item	Type of Survey	Product Type	Extent	Accessibility	Condition	Surface Treatment	Asbestos Type	Sample	Material Assessment Score	Photo
Floor 0 - Disabled Wc - 088 - Ceiling Tiles	Refurb-demolition	Organic	-	Medium	Good Condition	N/A	NAD	039 (Visually Consistent)	No Asbestos Detected	
Floor 0 - Disabled Wc - 089 - Ceiling Tiles	Refurb-demolition	Organic	-	Medium	Good Condition	N/A	NAD	039 (Visually Consistent)	No Asbestos Detected	
Floor 0 - Corridor - 092 - Mastic	Refurb-demolition	Organic	-	Difficult	Good Condition	N/A	NAD	040 (Visually Consistent)	No Asbestos Detected	
Floor 0 - Cellar - 094 - Sink Pad	Refurb-demolition	Bitumen/Felts	3no	Difficult	Good Condition	Bitumen	Chrysotile (white)	041	2	
Floor 0 - Electrical Cupboard - 096 - Panel	Refurb-demolition	Organic	-	Difficult	Good Condition	N/A	NAD	039 (Visually Consistent)	No Asbestos Detected	
Floor 0 - Stairwell - 098 - Floor Covering	Refurb-demolition	Organic	-	Easy	Good Condition	N/A	NAD	033 (Visually Consistent)	No Asbestos Detected	
Floor 0 - Stairwell - 098 - Stair Nosing	Refurb-demolition	Organic	-	Easy	Good Condition	N/A	NAD	034	No Asbestos Detected	



Location/Item	Type of Survey	Product Type	Extent	Accessibility	Condition	Surface Treatment	Asbestos Type	Sample	Material Assessment Score	Photo
Floor 0 - Stairwell - 098 - Bulkhead	Refurb-demolition	Organic	-	Medium	Good Condition	N/A	NAD	035	No Asbestos Detected	
Floor 0 - Stairwell - 098 - Ceiling Tiles	Refurb-demolition	Organic	-	Difficult	Good Condition	N/A	NAD	032 (Visually Consistent)	No Asbestos Detected	
Floor 0 - Lift Shaft - 100 - No Access	Refurb-demolition	Unknown	No Access	Difficult	High Damage	No Access	Presumed Asbestos	-	No Access	
Floor 1 - Entrance Lobby - 033 - Mastic	Refurb-demolition	Organic	-	Difficult	Good Condition	N/A	NAD	038 (Visually Consistent)	No Asbestos Detected	
Floor 1 - Entrance Lobby - 033 - Infill	Refurb-demolition	Organic	-	Easy	Good Condition	N/A	NAD	043	No Asbestos Detected	
Floor 1 - Cafe - 036 - Wall Panel	Refurb-demolition	Organic	-	Difficult	Good Condition	N/A	NAD	031 (Visually Consistent)	No Asbestos Detected	
Floor 1 - Cafe - 036 - Panel	Refurb-demolition	Organic	-	Easy	Good Condition	N/A	NAD	031 (Visually Consistent)	No Asbestos Detected	
Floor 1 - Cafe - 036 - Boxing	Refurb-demolition	Organic	-	Easy	Good Condition	N/A	NAD	031 (Visually Consistent)	No Asbestos Detected	

Location/Item	Type of Survey	Product Type	Extent	Accessibility	Condition	Surface Treatment	Asbestos Type	Sample	Material Assessment Score	Photo
Floor 1 - Cafe - 036 - Ceiling Tiles	Refurb-demolition	Organic	-	Medium	Good Condition	N/A	NAD	036	No Asbestos Detected	
Floor 1 - Corridor - 038 - Mastic	Refurb-demolition	Organic	-	Difficult	Good Condition	N/A	NAD	038	No Asbestos Detected	
Floor 1 - Office - 040 - Sink Pad	Refurb-demolition	Organic	-	Difficult	Good Condition	N/A	NAD	037	No Asbestos Detected	
Floor 1 - Landing - 047 - Ceiling Tiles	Refurb-demolition	Organic	-	Medium	Good Condition	N/A	NAD	032 (Visually Consistent)	No Asbestos Detected	
Floor 1 - Cupboard - 048 - Floor Covering	Refurb-demolition	Organic	-	Easy	Good Condition	N/A	NAD	033 (Visually Consistent)	No Asbestos Detected	
Floor 1 - Cupboard - 048 - Ceiling Tiles	Refurb-demolition	Organic	-	Medium	Good Condition	N/A	NAD	032 (Visually Consistent)	No Asbestos Detected	
Floor 1 - Corridor - 049 - Boxing	Refurb-demolition	Organic	-	Medium	Good Condition	N/A	NAD	031	No Asbestos Detected	

Location/Item	Type of Survey	Product Type	Extent	Accessibility	Condition	Surface Treatment	Asbestos Type	Sample	Material Assessment Score	Photo
Floor 1 - Kitchen - 050 - Sink	Refurb-demolition	Organic	-	Medium	Good Condition	N/A	NAD	026	No Asbestos Detected	
Floor 1 - Kitchen - 050 - Roof Felt	Refurb-demolition	Organic	-	Difficult	Good Condition	N/A	NAD	027	No Asbestos Detected	
Floor 1 - Electrical Cupboard - 057 - Panel	Refurb-demolition	Organic	-	Difficult	Good Condition	N/A	NAD	028	No Asbestos Detected	
Floor 1 - Kitchen - 058 - Sink	Refurb-demolition	Organic	-	Medium	Good Condition	N/A	NAD	026 (Visually Consistent)	No Asbestos Detected	
Floor 1 - Bar - 060 - Ceiling Tiles	Refurb-demolition	Organic	-	Medium	Good Condition	N/A	NAD	028 (Visually Consistent)	No Asbestos Detected	
Floor 1 - Bar - 060 - Sink	Refurb-demolition	Bitumen/Felts	2no	Difficult		Resins	NAD	029	No Asbestos Detected	
Floor 1 - Landing - 062 - Ceiling Void	Refurb-demolition	Organic	-	Difficult	Good Condition	N/A	NAD	032	No Asbestos Detected	

Location/Item	Type of Survey	Product Type	Extent	Accessibility	Condition	Surface Treatment	Asbestos Type	Sample	Material Assessment Score	Photo
Floor 1 - Landing - 062 - Floor Covering	Refurb-demolition	Organic	-	Easy	Good Condition	N/A	NAD	033	No Asbestos Detected	
Floor 1 - Corridor - 064 - Wall Panel	Refurb-demolition	Organic	-	Medium	Good Condition	N/A	NAD	031 (Visually Consistent)	No Asbestos Detected	
Floor 1 - Corridor - 064 - Mastic	Refurb-demolition	Organic	-	Difficult	Good Condition	N/A	NAD	030	No Asbestos Detected	
Floor 2 - Tank Room - 001 - Gaskets	Refurb-demolition	Asbestos Textiles	Throughout	Medium	Low Damage	Asbestos Textiles	Chrysotile (white)	005	6	
Floor 2 - Tank Room - 001 - Pipe Insulation	Refurb-demolition	Organic	-	Medium	Good Condition	N/A	NAD	006	No Asbestos Detected	
Floor 2 - Tank Room - 001 - Pipe Insulation	Refurb-demolition	Organic	-	Medium	Good Condition	N/A	NAD	007	No Asbestos Detected	
Floor 2 - Tank Room - 001 - Pipe Insulation	Refurb-demolition	Organic	-	Medium	Good Condition	N/A	NAD	008	No Asbestos Detected	

Location/Item	Type of Survey	Product Type	Extent	Accessibility	Condition	Surface Treatment	Asbestos Type	Sample	Material Assessment Score	Photo
Floor 2 - Tank Room - 001 - Pipe Insulation	Refurb-demolition	Organic	-	Medium	Good Condition	N/A	NAD	009	No Asbestos Detected	
Floor 2 - Tank Room - 001 - Pipe Insulation	Refurb-demolition	Organic	-	Medium	Good Condition	N/A	NAD	010	No Asbestos Detected	
Floor 2 - Tank Room - 001 - Pipe Insulation	Refurb-demolition	Organic	-	Medium	Good Condition	N/A	NAD	011	No Asbestos Detected	
Floor 2 - Tank Room - 001 - Pipe Insulation	Refurb-demolition	Organic	-	Medium	Good Condition	N/A	NAD	012	No Asbestos Detected	
Floor 2 - Tank Room - 001 - Pipe Insulation	Refurb-demolition	Organic	-	Medium	Good Condition	N/A	NAD	013	No Asbestos Detected	
Floor 2 - Tank Room - 001 - Pipe Insulation	Refurb-demolition	Organic	-	Medium	Good Condition	N/A	NAD	014	No Asbestos Detected	
Floor 2 - Tank Room - 001 - Pipe Insulation	Refurb-demolition	Organic	-	Medium	Good Condition	N/A	NAD	015	No Asbestos Detected	

Location/Item	Type of Survey	Product Type	Extent	Accessibility	Condition	Surface Treatment	Asbestos Type	Sample	Material Assessment Score	Photo
Floor 2 - Tank Room - 001 - Debris	Refurb-demolition	Organic	-	Easy	Good Condition	N/A	NAD	016	No Asbestos Detected	
Floor 2 - Tank Room - 001 - Floor	Refurb-demolition	Organic	-	Easy	Good Condition	N/A	NAD	017	No Asbestos Detected	
Floor 2 - Tank Room - 001 - Columns	Refurb-demolition	Organic	-	Easy	Good Condition	N/A	NAD	004	No Asbestos Detected	
Floor 99 - External - 501 - Columns	Refurb-demolition	Organic	-	Medium	Good Condition	N/A	NAD	002	No Asbestos Detected	
Floor 99 - External - 501 - Promenade Tiles	Refurb-demolition	Organic	-	Easy	Good Condition	N/A	NAD	003	No Asbestos Detected	

5.0 Non Asbestos Register

These items have been surveyed by OHS Ltd for the survey type stated and they are not suspected to be ACM's.

Building	Floor - Location	Item	Material	Survey Type
Temple Park Leisure Centre	0 - Corridor - 010	Floor	Concrete	Refurb-demolition
Temple Park Leisure Centre	0 - Corridor - 010	Ducting Insulation	MMMF	Refurb-demolition
Temple Park Leisure Centre	0 - Corridor - 010	Pipe Work	Metal	Refurb-demolition
Temple Park Leisure Centre	0 - Corridor - 010	Ducting	Metal	Refurb-demolition
Temple Park Leisure Centre	0 - Corridor - 010	Ceiling	Concrete	Refurb-demolition
Temple Park Leisure Centre	0 - Corridor - 010	Columns	Concrete	Refurb-demolition
Temple Park Leisure Centre	0 - Corridor - 010	Walls	Plasterboard	Refurb-demolition
Temple Park Leisure Centre	0 - Corridor - 010	Mastic	Organic	Refurb-demolition
Temple Park Leisure Centre	0 - Corridor - 010	Floor Tiles	Stone/Ceramic Tiles	Refurb-demolition
Temple Park Leisure Centre	0 - Corridor - 010	Beams	Concrete	Refurb-demolition
Temple Park Leisure Centre	0 - Corridor - 010	Skirting	Timber	Refurb-demolition
Temple Park Leisure Centre	0 - Corridor - 010	Door And Frame	Metal	Refurb-demolition
Temple Park Leisure Centre	0 - Corridor - 010	Door And Frame	Timber	Refurb-demolition
Temple Park Leisure Centre	0 - Corridor - 010	Wall Tiles	Stone/Ceramic Tiles	Refurb-demolition
Temple Park Leisure Centre	0 - Corridor - 010	Walls	Brick Block Walls	Refurb-demolition
Temple Park Leisure Centre	0 - Corridor - 010	Ceiling Tiles	MMMF	Refurb-demolition
Temple Park Leisure Centre	0 - Corridor - 010	Floor Panel	Metal	Refurb-demolition
Temple Park Leisure Centre	0 - Corridor - 010	Pipe Insulation	MMMF	Refurb-demolition
Temple Park Leisure Centre	0 - Plant Room - 011	Floor	Concrete	Refurb-demolition
Temple Park Leisure Centre	0 - Plant Room - 011	Walls	Brick Block Walls	Refurb-demolition
Temple Park Leisure Centre	0 - Plant Room - 011	Door And Frame	Metal	Refurb-demolition
Temple Park Leisure Centre	0 - Plant Room - 011	Pipe Insulation	Organic	Refurb-demolition
Temple Park Leisure Centre	0 - Plant Room - 011	Debris	Organic	Refurb-demolition
Temple Park Leisure Centre	0 - Plant Room - 011	Pipe Work	Metal	Refurb-demolition
Temple Park Leisure Centre	0 - Plant Room - 011	Ducting	Metal	Refurb-demolition
Temple Park Leisure Centre	0 - Plant Room - 011	Air Conditioning Unit	Non Asbestos	Refurb-demolition
Temple Park Leisure Centre	0 - Plant Room - 011	Ceiling	Concrete	Refurb-demolition
Temple Park Leisure Centre	0 - Lobby - 012	Pipe Insulation	MMMF	Refurb-demolition

Building	Floor - Location	Item	Material	Survey Type
Temple Park Leisure Centre	0 - Lobby - 012	Skirting	Timber	Refurb-demolition
Temple Park Leisure Centre	0 - Lobby - 012	Ducting	Metal	Refurb-demolition
Temple Park Leisure Centre	0 - Lobby - 012	Pipe Work	Metal	Refurb-demolition
Temple Park Leisure Centre	0 - Lobby - 012	Columns	Concrete	Refurb-demolition
Temple Park Leisure Centre	0 - Lobby - 012	Beams	Concrete	Refurb-demolition
Temple Park Leisure Centre	0 - Lobby - 012	Ceiling	Concrete	Refurb-demolition
Temple Park Leisure Centre	0 - Lobby - 012	Ceiling Void	Non Asbestos	Refurb-demolition
Temple Park Leisure Centre	0 - Lobby - 012	Ceiling	Plasterboard	Refurb-demolition
Temple Park Leisure Centre	0 - Lobby - 012	Floor	Concrete	Refurb-demolition
Temple Park Leisure Centre	0 - Lobby - 012	Wall Cavity	Non Asbestos	Refurb-demolition
Temple Park Leisure Centre	0 - Lobby - 012	Walls	Plasterboard	Refurb-demolition
Temple Park Leisure Centre	0 - Lobby - 012	Walls	Brick Block Walls	Refurb-demolition
Temple Park Leisure Centre	0 - Lobby - 012	Door And Frame	Timber	Refurb-demolition
Temple Park Leisure Centre	0 - Gymnasium - 013	Floor Covering	Non Asbestos	Refurb-demolition
Temple Park Leisure Centre	0 - Gymnasium - 013	Wall Cavity	Non Asbestos	Refurb-demolition
Temple Park Leisure Centre	0 - Gymnasium - 013	Floor	Timber	Refurb-demolition
Temple Park Leisure Centre	0 - Gymnasium - 013	Pipe Work	Metal	Refurb-demolition
Temple Park Leisure Centre	0 - Gymnasium - 013	Pipe Insulation	MMMF	Refurb-demolition
Temple Park Leisure Centre	0 - Gymnasium - 013	Ducting Insulation	MMMF	Refurb-demolition
Temple Park Leisure Centre	0 - Gymnasium - 013	Ceiling Tiles	MMMF	Refurb-demolition
Temple Park Leisure Centre	0 - Gymnasium - 013	Walls	Plasterboard	Refurb-demolition
Temple Park Leisure Centre	0 - Gymnasium - 013	Ceiling	Plasterboard	Refurb-demolition
Temple Park Leisure Centre	0 - Gymnasium - 013	Walls	Brick Block Walls	Refurb-demolition
Temple Park Leisure Centre	0 - Gymnasium - 013	Ceiling	Concrete	Refurb-demolition
Temple Park Leisure Centre	0 - Gymnasium - 013	Ducting	Metal	Refurb-demolition
Temple Park Leisure Centre	0 - Gymnasium - 013	Ceiling Void	Non Asbestos	Refurb-demolition
Temple Park Leisure Centre	0 - Stairwell - 014	Pipe	Metal	Refurb-demolition
Temple Park Leisure Centre	0 - Stairwell - 014	Downpipes	Non Asbestos	Refurb-demolition
Temple Park Leisure Centre	0 - Stairwell - 014	Pipe Insulation	Foam	Refurb-demolition
Temple Park Leisure Centre	0 - Stairwell - 014	Riser Void	Non Asbestos	Refurb-demolition
Temple Park Leisure Centre	0 - Stairwell - 014	Riser	Timber	Refurb-demolition

Building	Floor - Location	Item	Material	Survey Type
Temple Park Leisure Centre	0 - Stairwell - 014	Skirting	Timber	Refurb-demolition
Temple Park Leisure Centre	0 - Stairwell - 014	Bulkhead	Timber	Refurb-demolition
Temple Park Leisure Centre	0 - Stairwell - 014	Roof	Metal	Refurb-demolition
Temple Park Leisure Centre	0 - Stairwell - 014	Floor Covering	Organic	Refurb-demolition
Temple Park Leisure Centre	0 - Stairwell - 014	Bulkhead	Organic	Refurb-demolition
Temple Park Leisure Centre	0 - Stairwell - 014	Ceiling Tiles	Organic	Refurb-demolition
Temple Park Leisure Centre	0 - Stairwell - 014	Walls	Brick Block Walls	Refurb-demolition
Temple Park Leisure Centre	0 - Stairwell - 014	Beams	Concrete	Refurb-demolition
Temple Park Leisure Centre	0 - Stairwell - 014	Stair Nosing	Organic	Refurb-demolition
Temple Park Leisure Centre	0 - Stairwell - 014	Ceiling	Concrete	Refurb-demolition
Temple Park Leisure Centre	0 - Stairwell - 014	Beams	Metal	Refurb-demolition
Temple Park Leisure Centre	0 - Stairwell - 014	Skirting	Timber	Refurb-demolition
Temple Park Leisure Centre	0 - Stairwell - 014	Columns	Metal	Refurb-demolition
Temple Park Leisure Centre	0 - Stairwell - 014	Roof	Metal	Refurb-demolition
Temple Park Leisure Centre	0 - Stairwell - 014	Door And Frame	Timber	Refurb-demolition
Temple Park Leisure Centre	0 - Stairwell - 014	Floor	Concrete	Refurb-demolition
Temple Park Leisure Centre	0 - Stairwell - 014	Walls	Non Asbestos	Refurb-demolition
Temple Park Leisure Centre	0 - Stairwell - 014	Stairs	Concrete	Refurb-demolition
Temple Park Leisure Centre	0 - Stairwell - 014	Fire Door	Metal	Refurb-demolition
Temple Park Leisure Centre	0 - Stairwell - 014	Columns	Concrete	Refurb-demolition
Temple Park Leisure Centre	0 - Corridor - 015	Riser	Timber	Refurb-demolition
Temple Park Leisure Centre	0 - Corridor - 015	Infill	Timber	Refurb-demolition
Temple Park Leisure Centre	0 - Corridor - 015	Walls	Brick Block Walls	Refurb-demolition
Temple Park Leisure Centre	0 - Corridor - 015	Floor	Concrete	Refurb-demolition
Temple Park Leisure Centre	0 - Corridor - 015	Floor Tiles	Stone/Ceramic Tiles	Refurb-demolition
Temple Park Leisure Centre	0 - Corridor - 015	Skirting	Timber	Refurb-demolition
Temple Park Leisure Centre	0 - Corridor - 015	Downpipes	Non Asbestos	Refurb-demolition
Temple Park Leisure Centre	0 - Corridor - 015	Door And Frame	Timber	Refurb-demolition
Temple Park Leisure Centre	0 - Corridor - 015	Insulation	MMMF	Refurb-demolition
Temple Park Leisure Centre	0 - Corridor - 015	Ceiling Tiles	MMMF	Refurb-demolition
Temple Park Leisure Centre	0 - Corridor - 015	Riser Void	Non Asbestos	Refurb-demolition

Building	Floor - Location	Item	Material	Survey Type
Temple Park Leisure Centre	0 - Corridor - 015	Pipe Work	Metal	Refurb-demolition
Temple Park Leisure Centre	0 - Corridor - 015	Ducting	Metal	Refurb-demolition
Temple Park Leisure Centre	0 - Corridor - 015	Beams	Concrete	Refurb-demolition
Temple Park Leisure Centre	0 - Corridor - 015	Ceiling	Concrete	Refurb-demolition
Temple Park Leisure Centre	0 - Office - 016	Skirting	Timber	Refurb-demolition
Temple Park Leisure Centre	0 - Office - 016	Walls	Brick Block Walls	Refurb-demolition
Temple Park Leisure Centre	0 - Office - 016	Wall Panel	Plasterboard	Refurb-demolition
Temple Park Leisure Centre	0 - Office - 016	Door And Frame	Timber	Refurb-demolition
Temple Park Leisure Centre	0 - Office - 016	Floor	Concrete	Refurb-demolition
Temple Park Leisure Centre	0 - Office - 016	Floor Covering	Non Asbestos	Refurb-demolition
Temple Park Leisure Centre	0 - Office - 016	Ceiling Tiles	MMMF	Refurb-demolition
Temple Park Leisure Centre	0 - Office - 016	Riser	Timber	Refurb-demolition
Temple Park Leisure Centre	0 - Office - 016	Heating Unit	Metal	Refurb-demolition
Temple Park Leisure Centre	0 - Office - 016	Heating Unit	Non Asbestos	Refurb-demolition
Temple Park Leisure Centre	0 - Office - 016	Ceiling	Concrete	Refurb-demolition
Temple Park Leisure Centre	0 - Office - 016	Beams	Concrete	Refurb-demolition
Temple Park Leisure Centre	0 - Office - 016	Columns	Concrete	Refurb-demolition
Temple Park Leisure Centre	0 - Office - 016	Pipe Work	Metal	Refurb-demolition
Temple Park Leisure Centre	0 - Office - 016	Riser Void	Non Asbestos	Refurb-demolition
Temple Park Leisure Centre	0 - Office - 016	Ducting	Metal	Refurb-demolition
Temple Park Leisure Centre	0 - Store Room - 017	Floor	Concrete	Refurb-demolition
Temple Park Leisure Centre	0 - Store Room - 017	Door And Frame	Metal	Refurb-demolition
Temple Park Leisure Centre	0 - Store Room - 017	Ducting	Metal	Refurb-demolition
Temple Park Leisure Centre	0 - Store Room - 017	Ceiling	Concrete	Refurb-demolition
Temple Park Leisure Centre	0 - Store Room - 017	Electrics	Non Asbestos	Refurb-demolition
Temple Park Leisure Centre	0 - Store Room - 017	Pipe Work	Metal	Refurb-demolition
Temple Park Leisure Centre	0 - Store Room - 017	Sink Pad	Organic	Refurb-demolition
Temple Park Leisure Centre	0 - Store Room - 017	Door And Frame	Timber	Refurb-demolition
Temple Park Leisure Centre	0 - Store Room - 017	Walls	Brick Block Walls	Refurb-demolition
Temple Park Leisure Centre	0 - Store Room - 018	Pipe Work	Metal	Refurb-demolition
Temple Park Leisure Centre	0 - Store Room - 018	Floor	Stone/Ceramic Tiles	Refurb-demolition

Building	Floor - Location	Item	Material	Survey Type
Temple Park Leisure Centre	0 - Store Room - 018	Walls	Brick Block Walls	Refurb-demolition
Temple Park Leisure Centre	0 - Store Room - 018	Door And Frame	Timber	Refurb-demolition
Temple Park Leisure Centre	0 - Store Room - 018	Suspended Ceiling	Foam	Refurb-demolition
Temple Park Leisure Centre	0 - Store Room - 018	Ceiling	Concrete	Refurb-demolition
Temple Park Leisure Centre	0 - Store Room - 018	Pipe Insulation	Foam	Refurb-demolition
Temple Park Leisure Centre	0 - Cupboard - 019	Door And Frame	Timber	Refurb-demolition
Temple Park Leisure Centre	0 - Cupboard - 019	Ceiling	Concrete	Refurb-demolition
Temple Park Leisure Centre	0 - Cupboard - 019	Suspended Ceiling	Foam	Refurb-demolition
Temple Park Leisure Centre	0 - Cupboard - 019	Floor	Stone/Ceramic Tiles	Refurb-demolition
Temple Park Leisure Centre	0 - Cupboard - 019	Walls	Brick Block Walls	Refurb-demolition
Temple Park Leisure Centre	0 - Kitchen - 020	Door And Frame	Timber	Refurb-demolition
Temple Park Leisure Centre	0 - Kitchen - 020	Walls	Brick Block Walls	Refurb-demolition
Temple Park Leisure Centre	0 - Kitchen - 020	Chiller Unit	Non Asbestos	Refurb-demolition
Temple Park Leisure Centre	0 - Kitchen - 020	Wall Tiles	Stone/Ceramic Tiles	Refurb-demolition
Temple Park Leisure Centre	0 - Kitchen - 020	Pipe Work	Metal	Refurb-demolition
Temple Park Leisure Centre	0 - Kitchen - 020	Sink	Metal	Refurb-demolition
Temple Park Leisure Centre	0 - Kitchen - 020	Ceiling	Concrete	Refurb-demolition
Temple Park Leisure Centre	0 - Kitchen - 020	Suspended Ceiling	Foam	Refurb-demolition
Temple Park Leisure Centre	0 - Kitchen - 020	Floor	Stone/Ceramic Tiles	Refurb-demolition
Temple Park Leisure Centre	0 - Kitchen - 020	Electrics	Non Asbestos	Refurb-demolition
Temple Park Leisure Centre	0 - Kitchen - 020	Ducting	Non Asbestos	Refurb-demolition
Temple Park Leisure Centre	0 - Cleaner's Cupboard - 021	Ceiling	Concrete	Refurb-demolition
Temple Park Leisure Centre	0 - Cleaner's Cupboard - 021	Pipe Insulation	Metal	Refurb-demolition
Temple Park Leisure Centre	0 - Cleaner's Cupboard - 021	Floor	Concrete	Refurb-demolition
Temple Park Leisure Centre	0 - Cleaner's Cupboard - 021	Beams	Concrete	Refurb-demolition
Temple Park Leisure Centre	0 - Cleaner's Cupboard - 021	Plant Equipment	Non Asbestos	Refurb-demolition
Temple Park Leisure Centre	0 - Cleaner's Cupboard - 021	Columns	Concrete	Refurb-demolition
Temple Park Leisure Centre	0 - Cleaner's Cupboard - 021	Downpipes	Non Asbestos	Refurb-demolition
Temple Park Leisure Centre	0 - Cleaner's Cupboard - 021	Door And Frame	Timber	Refurb-demolition
Temple Park Leisure Centre	0 - Cleaner's Cupboard - 021	Walls	Brick Block Walls	Refurb-demolition
Temple Park Leisure Centre	0 - Cleaner's Cupboard - 021	Pipe Insulation	MMMF	Refurb-demolition

Building	Floor - Location	Item	Material	Survey Type
Temple Park Leisure Centre	0 - Cleaner's Cupboard - 021	Insulation	MMMF	Refurb-demolition
Temple Park Leisure Centre	0 - Office - 022	Pipe Work	Metal	Refurb-demolition
Temple Park Leisure Centre	0 - Office - 022	Ceiling Tiles	MMMF	Refurb-demolition
Temple Park Leisure Centre	0 - Office - 022	Beams	Concrete	Refurb-demolition
Temple Park Leisure Centre	0 - Office - 022	Pipe Insulation	MMMF	Refurb-demolition
Temple Park Leisure Centre	0 - Office - 022	Ducting Insulation	MMMF	Refurb-demolition
Temple Park Leisure Centre	0 - Office - 022	Ducting	Metal	Refurb-demolition
Temple Park Leisure Centre	0 - Office - 022	Walls	Brick Block Walls	Refurb-demolition
Temple Park Leisure Centre	0 - Office - 022	Walls	Plasterboard	Refurb-demolition
Temple Park Leisure Centre	0 - Office - 022	Skirting	Timber	Refurb-demolition
Temple Park Leisure Centre	0 - Office - 022	Columns	Concrete	Refurb-demolition
Temple Park Leisure Centre	0 - Office - 022	Floor	Concrete	Refurb-demolition
Temple Park Leisure Centre	0 - Office - 022	Floor Covering	Non Asbestos	Refurb-demolition
Temple Park Leisure Centre	0 - Office - 022	Door And Frame	Timber	Refurb-demolition
Temple Park Leisure Centre	0 - Office - 022	Safe	Non Asbestos	Refurb-demolition
Temple Park Leisure Centre	0 - Office - 022	Ceiling	Concrete	Refurb-demolition
Temple Park Leisure Centre	0 - Electrical Switchroom - 023	Ceiling	Concrete	Refurb-demolition
Temple Park Leisure Centre	0 - Electrical Switchroom - 023	Floor Panel	Metal	Refurb-demolition
Temple Park Leisure Centre	0 - Electrical Switchroom - 023	Floor	Concrete	Refurb-demolition
Temple Park Leisure Centre	0 - Electrical Switchroom - 023	Electrical Equipment	Non Asbestos	Refurb-demolition
Temple Park Leisure Centre	0 - Electrical Switchroom - 023	Door And Frame	Timber	Refurb-demolition
Temple Park Leisure Centre	0 - Electrical Switchroom - 023	Walls	Brick Block Walls	Refurb-demolition
Temple Park Leisure Centre	0 - Electrical Switchroom - 023	Columns	Concrete	Refurb-demolition
Temple Park Leisure Centre	0 - Electrical Cupboard - 023	Mastic	Non Asbestos	Refurb-demolition
Temple Park Leisure Centre	0 - Electrical Switchroom - 023	Panel	Organic	Refurb-demolition
Temple Park Leisure Centre	0 - Electrical Cupboard - 023	Insulation	MMMF	Refurb-demolition
Temple Park Leisure Centre	0 - Electrical Switchroom - 023	Beams	Concrete	Refurb-demolition
Temple Park Leisure Centre	0 - Corridor - 024	Door And Frame	Timber	Refurb-demolition
Temple Park Leisure Centre	0 - Corridor - 024	Skirting	Timber	Refurb-demolition
Temple Park Leisure Centre	0 - Corridor - 024	Floor	Concrete	Refurb-demolition
Temple Park Leisure Centre	0 - Corridor - 024	Floor Tiles	Stone/Ceramic Tiles	Refurb-demolition

Building	Floor - Location	Item	Material	Survey Type
Temple Park Leisure Centre	0 - Corridor - 024	Electrical Equipment	Non Asbestos	Refurb-demolition
Temple Park Leisure Centre	0 - Corridor - 024	Window Frame	Timber	Refurb-demolition
Temple Park Leisure Centre	0 - Corridor - 024	Ceiling Tiles	MMMF	Refurb-demolition
Temple Park Leisure Centre	0 - Corridor - 024	Ceiling	Concrete	Refurb-demolition
Temple Park Leisure Centre	0 - Corridor - 024	Pipe Insulation	MMMF	Refurb-demolition
Temple Park Leisure Centre	0 - Corridor - 024	Pipe Work	Metal	Refurb-demolition
Temple Park Leisure Centre	0 - Corridor - 024	Ducting Insulation	MMMF	Refurb-demolition
Temple Park Leisure Centre	0 - Corridor - 024	Ducting	Metal	Refurb-demolition
Temple Park Leisure Centre	0 - Corridor - 024	Ceiling Tiles	MMMF	Refurb-demolition
Temple Park Leisure Centre	0 - Corridor - 024	Beams	Concrete	Refurb-demolition
Temple Park Leisure Centre	0 - Corridor - 024	Infill	Timber	Refurb-demolition
Temple Park Leisure Centre	0 - Corridor - 024	Walls	Brick Block Walls	Refurb-demolition
Temple Park Leisure Centre	0 - Corridor - 024	Mastic	Organic	Refurb-demolition
Temple Park Leisure Centre	0 - Corridor - 025	Skirting	Timber	Refurb-demolition
Temple Park Leisure Centre	0 - Corridor - 025	Ducting	Metal	Refurb-demolition
Temple Park Leisure Centre	0 - Corridor - 025	Ducting Insulation	MMMF	Refurb-demolition
Temple Park Leisure Centre	0 - Corridor - 025	Infill	Timber	Refurb-demolition
Temple Park Leisure Centre	0 - Corridor - 025	Walls	Brick Block Walls	Refurb-demolition
Temple Park Leisure Centre	0 - Corridor - 025	Door And Frame	Timber	Refurb-demolition
Temple Park Leisure Centre	0 - Corridor - 025	Beams	Concrete	Refurb-demolition
Temple Park Leisure Centre	0 - Corridor - 025	Window Frame	Timber	Refurb-demolition
Temple Park Leisure Centre	0 - Corridor - 025	Floor	Concrete	Refurb-demolition
Temple Park Leisure Centre	0 - Corridor - 025	Columns	Concrete	Refurb-demolition
Temple Park Leisure Centre	0 - Corridor - 025	Ceiling	Concrete	Refurb-demolition
Temple Park Leisure Centre	0 - Corridor - 025	Floor Tiles	Stone/Ceramic Tiles	Refurb-demolition
Temple Park Leisure Centre	0 - Corridor - 025	Ceiling Tiles	MMMF	Refurb-demolition
Temple Park Leisure Centre	0 - Male Wc - 026	Floor	Concrete	Refurb-demolition
Temple Park Leisure Centre	0 - Male Wc - 026	Walls	Timber	Refurb-demolition
Temple Park Leisure Centre	0 - Male Wc - 026	Door And Frame	Timber	Refurb-demolition
Temple Park Leisure Centre	0 - Male Wc - 026	Boxing Void	Non Asbestos	Refurb-demolition
Temple Park Leisure Centre	0 - Male Wc - 026	Floor Tiles	Stone/Ceramic Tiles	Refurb-demolition

Building	Floor - Location	Item	Material	Survey Type
Temple Park Leisure Centre	0 - Male Wc - 026	Panelling	Timber	Refurb-demolition
Temple Park Leisure Centre	0 - Male Wc - 026	Walls	Brick Block Walls	Refurb-demolition
Temple Park Leisure Centre	0 - Male Wc - 026	Columns	Concrete	Refurb-demolition
Temple Park Leisure Centre	0 - Male Wc - 026	Ducting	Metal	Refurb-demolition
Temple Park Leisure Centre	0 - Male Wc - 026	Boxing	Timber	Refurb-demolition
Temple Park Leisure Centre	0 - Male Wc - 026	Ceiling Tiles	Organic	Refurb-demolition
Temple Park Leisure Centre	0 - Male Wc - 026	Toilet Cistern	Non Asbestos	Refurb-demolition
Temple Park Leisure Centre	0 - Male Wc - 026	Pipe Work	Non Asbestos	Refurb-demolition
Temple Park Leisure Centre	0 - Male Wc - 026	Ceiling Tiles	MMMF	Refurb-demolition
Temple Park Leisure Centre	0 - Male Wc - 026	Insulation	MMMF	Refurb-demolition
Temple Park Leisure Centre	0 - Male Wc - 026	Pipe Insulation	MMMF	Refurb-demolition
Temple Park Leisure Centre	0 - Male Wc - 026	Ducting Insulation	MMMF	Refurb-demolition
Temple Park Leisure Centre	0 - Male Wc - 026	Ceiling	Concrete	Refurb-demolition
Temple Park Leisure Centre	0 - Male Wc - 026	Pipe Work	Metal	Refurb-demolition
Temple Park Leisure Centre	0 - Male Wc - 026	Toilet Seat	Non Asbestos	Refurb-demolition
Temple Park Leisure Centre	0 - Female Wc - 027	Toilet Seat	Non Asbestos	Refurb-demolition
Temple Park Leisure Centre	0 - Female Wc - 027	Toilet Cistern	Non Asbestos	Refurb-demolition
Temple Park Leisure Centre	0 - Female Wc - 027	Pipe Insulation	MMMF	Refurb-demolition
Temple Park Leisure Centre	0 - Female Wc - 027	Ducting	Metal	Refurb-demolition
Temple Park Leisure Centre	0 - Female Wc - 027	Beams	Concrete	Refurb-demolition
Temple Park Leisure Centre	0 - Female Wc - 027	Ceiling	Concrete	Refurb-demolition
Temple Park Leisure Centre	0 - Female Wc - 027	Boxing Void	Non Asbestos	Refurb-demolition
Temple Park Leisure Centre	0 - Female Wc - 027	Ducting Insulation	MMMF	Refurb-demolition
Temple Park Leisure Centre	0 - Female Wc - 027	Ceiling Tiles	Organic	Refurb-demolition
Temple Park Leisure Centre	0 - Female Wc - 027	Wall Tiles	Stone/Ceramic Tiles	Refurb-demolition
Temple Park Leisure Centre	0 - Female Wc - 027	Walls	Brick Block Walls	Refurb-demolition
Temple Park Leisure Centre	0 - Female Wc - 027	Panelling	Timber	Refurb-demolition
Temple Park Leisure Centre	0 - Female Wc - 027	Ceiling Tiles	MMMF	Refurb-demolition
Temple Park Leisure Centre	0 - Female Wc - 027	Pipe	Non Asbestos	Refurb-demolition
Temple Park Leisure Centre	0 - Female Wc - 027	Walls	Timber	Refurb-demolition
Temple Park Leisure Centre	0 - Female Wc - 027	Floor	Concrete	Refurb-demolition

Building	Floor - Location	Item	Material	Survey Type
Temple Park Leisure Centre	0 - Female Wc - 027	Floor Tiles	Stone/Ceramic Tiles	Refurb-demolition
Temple Park Leisure Centre	0 - Female Wc - 027	Door And Frame	Timber	Refurb-demolition
Temple Park Leisure Centre	0 - Female Wc - 027	Boxing	Timber	Refurb-demolition
Temple Park Leisure Centre	0 - Female Wc - 027	Pipe	Metal	Refurb-demolition
Temple Park Leisure Centre	0 - Female Wc - 027	Pipe Insulation	Foam	Refurb-demolition
Temple Park Leisure Centre	0 - Changing Room - 046	Insulation	MMMF	Refurb-demolition
Temple Park Leisure Centre	0 - Changing Room - 046	Walls	Brick Block Walls	Refurb-demolition
Temple Park Leisure Centre	0 - Changing Room - 046	Ceiling	Concrete	Refurb-demolition
Temple Park Leisure Centre	0 - Changing Room - 046	Panelling	Timber	Refurb-demolition
Temple Park Leisure Centre	0 - Changing Room - 046	Beams	Concrete	Refurb-demolition
Temple Park Leisure Centre	0 - Changing Room - 046	Ducting	Metal	Refurb-demolition
Temple Park Leisure Centre	0 - Changing Room - 046	Wall Tiles	Stone/Ceramic Tiles	Refurb-demolition
Temple Park Leisure Centre	0 - Changing Room - 046	Door And Frame	Timber	Refurb-demolition
Temple Park Leisure Centre	0 - Changing Room - 046	Floor Tiles	Stone/Ceramic Tiles	Refurb-demolition
Temple Park Leisure Centre	0 - Changing Room - 046	Ceiling Tiles	MMMF	Refurb-demolition
Temple Park Leisure Centre	0 - Changing Room - 046	Cladding	Timber	Refurb-demolition
Temple Park Leisure Centre	0 - Changing Room - 046	Floor	Concrete	Refurb-demolition
Temple Park Leisure Centre	0 - Changing Room - 046	Columns	Concrete	Refurb-demolition
Temple Park Leisure Centre	0 - Changing Room - 046	Downpipes	Non Asbestos	Refurb-demolition
Temple Park Leisure Centre	0 - Changing Room - 046	Boxing	Plasterboard	Refurb-demolition
Temple Park Leisure Centre	0 - Changing Room - 046	Beams	Concrete	Refurb-demolition
Temple Park Leisure Centre	0 - Changing Room - 046	Insulation	MMMF	Refurb-demolition
Temple Park Leisure Centre	0 - Changing Room - 046	Door And Frame	Timber	Refurb-demolition
Temple Park Leisure Centre	0 - Changing Room - 046	Floor Tiles	Stone/Ceramic Tiles	Refurb-demolition
Temple Park Leisure Centre	0 - Changing Room - 046	Mastic	Organic	Refurb-demolition
Temple Park Leisure Centre	0 - Changing Room - 046	Packing	Timber	Refurb-demolition
Temple Park Leisure Centre	0 - Changing Room - 046	Ceiling	Concrete	Refurb-demolition
Temple Park Leisure Centre	0 - Changing Room - 046	Walls	Brick Block Walls	Refurb-demolition
Temple Park Leisure Centre	0 - Changing Room - 046	Wall Tiles	Stone/Ceramic Tiles	Refurb-demolition
Temple Park Leisure Centre	0 - Changing Room - 046	Floor Covering	Organic	Refurb-demolition
Temple Park Leisure Centre	0 - Changing Room - 046	Floor	Concrete	Refurb-demolition

Building	Floor - Location	Item	Material	Survey Type
Temple Park Leisure Centre	0 - Changing Room - 046	Ducting	Metal	Refurb-demolition
Temple Park Leisure Centre	0 - Changing Room - 048	Ceiling Tiles	Organic	Refurb-demolition
Temple Park Leisure Centre	0 - Changing Room - 048	Ceiling	Concrete	Refurb-demolition
Temple Park Leisure Centre	0 - Changing Room - 048	Walls	Brick Block Walls	Refurb-demolition
Temple Park Leisure Centre	0 - Changing Room - 048	Wall Tiles	Stone/Ceramic Tiles	Refurb-demolition
Temple Park Leisure Centre	0 - Changing Room - 048	Floor	Concrete	Refurb-demolition
Temple Park Leisure Centre	0 - Changing Room - 048	Door And Frame	Timber	Refurb-demolition
Temple Park Leisure Centre	0 - Changing Room - 048	Floor Tiles	Stone/Ceramic Tiles	Refurb-demolition
Temple Park Leisure Centre	0 - Plant Room - 049	Pipe Work	Non Asbestos	Refurb-demolition
Temple Park Leisure Centre	0 - Plant Room - 049	Floor	Concrete	Refurb-demolition
Temple Park Leisure Centre	0 - Plant Room - 049	Walls	Brick Block Walls	Refurb-demolition
Temple Park Leisure Centre	0 - Plant Room - 049	Pipe Work	Metal	Refurb-demolition
Temple Park Leisure Centre	0 - Plant Room - 049	Door And Frame	Timber	Refurb-demolition
Temple Park Leisure Centre	0 - Changing Room - 050	Pipe Insulation	MMMF	Refurb-demolition
Temple Park Leisure Centre	0 - Changing Room - 050	Walls	Brick Block Walls	Refurb-demolition
Temple Park Leisure Centre	0 - Changing Room - 050	Ceiling Tiles	Organic	Refurb-demolition
Temple Park Leisure Centre	0 - Changing Room - 050	Floor Tiles	Stone/Ceramic Tiles	Refurb-demolition
Temple Park Leisure Centre	0 - Changing Room - 050	Wall Tiles	Stone/Ceramic Tiles	Refurb-demolition
Temple Park Leisure Centre	0 - Changing Room - 050	Pipe Work	Metal	Refurb-demolition
Temple Park Leisure Centre	0 - Changing Room - 050	Beams	Concrete	Refurb-demolition
Temple Park Leisure Centre	0 - Changing Room - 050	Ceiling	Concrete	Refurb-demolition
Temple Park Leisure Centre	0 - Changing Room - 050	Door And Frame	Timber	Refurb-demolition
Temple Park Leisure Centre	0 - Changing Room - 050	Floor	Concrete	Refurb-demolition
Temple Park Leisure Centre	0 - Wc - 051	Pipe Insulation	MMMF	Refurb-demolition
Temple Park Leisure Centre	0 - Wc - 051	Boxing Void	Non Asbestos	Refurb-demolition
Temple Park Leisure Centre	0 - Wc - 051	Toilet Seat	Non Asbestos	Refurb-demolition
Temple Park Leisure Centre	0 - Wc - 051	Toilet Cistern	Non Asbestos	Refurb-demolition
Temple Park Leisure Centre	0 - Wc - 051	Floor Tiles	Stone/Ceramic Tiles	Refurb-demolition
Temple Park Leisure Centre	0 - Wc - 051	Floor	Concrete	Refurb-demolition
Temple Park Leisure Centre	0 - Wc - 051	Ducting	Metal	Refurb-demolition
Temple Park Leisure Centre	0 - Wc - 051	Panelling	Timber	Refurb-demolition

Building	Floor - Location	Item	Material	Survey Type
Temple Park Leisure Centre	0 - Wc - 051	Door And Frame	Timber	Refurb-demolition
Temple Park Leisure Centre	0 - Wc - 051	Beams	Concrete	Refurb-demolition
Temple Park Leisure Centre	0 - Wc - 051	Mastic	Organic	Refurb-demolition
Temple Park Leisure Centre	0 - Wc - 051	Pipe Work	Metal	Refurb-demolition
Temple Park Leisure Centre	0 - Wc - 051	Boxing	Timber	Refurb-demolition
Temple Park Leisure Centre	0 - Wc - 051	Walls	Brick Block Walls	Refurb-demolition
Temple Park Leisure Centre	0 - Wc - 051	Ceiling	Concrete	Refurb-demolition
Temple Park Leisure Centre	0 - Changing Room - 052	Downpipes	Non Asbestos	Refurb-demolition
Temple Park Leisure Centre	0 - Changing Room - 052	Ceiling Tiles	MMMF	Refurb-demolition
Temple Park Leisure Centre	0 - Changing Room - 052	Loose Insulation	MMMF	Refurb-demolition
Temple Park Leisure Centre	0 - Changing Room - 052	Boxing Void	Non Asbestos	Refurb-demolition
Temple Park Leisure Centre	0 - Changing Room - 052	Boxing	Plasterboard	Refurb-demolition
Temple Park Leisure Centre	0 - Changing Room - 052	Floor Covering	Stone/Ceramic Tiles	Refurb-demolition
Temple Park Leisure Centre	0 - Changing Room - 052	Floor	Concrete	Refurb-demolition
Temple Park Leisure Centre	0 - Changing Room - 052	Ducting	Metal	Refurb-demolition
Temple Park Leisure Centre	0 - Changing Room - 052	Door And Frame	Timber	Refurb-demolition
Temple Park Leisure Centre	0 - Changing Room - 052	Beam Cladding	Timber	Refurb-demolition
Temple Park Leisure Centre	0 - Changing Room - 052	Beams	Concrete	Refurb-demolition
Temple Park Leisure Centre	0 - Changing Room - 052	Columns	Concrete	Refurb-demolition
Temple Park Leisure Centre	0 - Changing Room - 052	Skirting	Stone/Ceramic Tiles	Refurb-demolition
Temple Park Leisure Centre	0 - Changing Room - 052	Walls	Brick Block Walls	Refurb-demolition
Temple Park Leisure Centre	0 - Corridor - 053	Pipe Insulation	Foam	Refurb-demolition
Temple Park Leisure Centre	0 - Corridor - 053	Floor	Concrete	Refurb-demolition
Temple Park Leisure Centre	0 - Corridor - 053	Fire Door	Metal	Refurb-demolition
Temple Park Leisure Centre	0 - Corridor - 053	Skirting	Timber	Refurb-demolition
Temple Park Leisure Centre	0 - Corridor - 053	Door And Frame	Timber	Refurb-demolition
Temple Park Leisure Centre	0 - Corridor - 053	Walls	Brick Block Walls	Refurb-demolition
Temple Park Leisure Centre	0 - Corridor - 053	Ceiling Tiles	MMMF	Refurb-demolition
Temple Park Leisure Centre	0 - Corridor - 053	Insulation	MMMF	Refurb-demolition
Temple Park Leisure Centre	0 - Corridor - 053	Columns	Concrete	Refurb-demolition
Temple Park Leisure Centre	0 - Corridor - 053	Pipe Work	Metal	Refurb-demolition

Building	Floor - Location	Item	Material	Survey Type
Temple Park Leisure Centre	0 - Corridor - 053	Floor Tiles	Stone/Ceramic Tiles	Refurb-demolition
Temple Park Leisure Centre	0 - Corridor - 053	Beams	Concrete	Refurb-demolition
Temple Park Leisure Centre	0 - Corridor - 053	Mastic	Organic	Refurb-demolition
Temple Park Leisure Centre	0 - Corridor - 053	Ceiling Tiles	Organic	Refurb-demolition
Temple Park Leisure Centre	0 - Corridor - 053	Ceiling	Concrete	Refurb-demolition
Temple Park Leisure Centre	0 - Corridor - 053	Walls	Plasterboard	Refurb-demolition
Temple Park Leisure Centre	0 - Hall - 054	Rain Water Goods	Non Asbestos	Refurb-demolition
Temple Park Leisure Centre	0 - Hall - 054	Fire Break	Non Asbestos	Refurb-demolition
Temple Park Leisure Centre	0 - Hall - 054	Ducting	Non Asbestos	Refurb-demolition
Temple Park Leisure Centre	0 - Hall - 054	Beams	Metal	Refurb-demolition
Temple Park Leisure Centre	0 - Hall - 054	Roof	Metal	Refurb-demolition
Temple Park Leisure Centre	0 - Hall - 054	Pipe Work	Non Asbestos	Refurb-demolition
Temple Park Leisure Centre	0 - Hall - 054	Walls	Brick Block Walls	Refurb-demolition
Temple Park Leisure Centre	0 - Hall - 054	Sky Light	Metal	Refurb-demolition
Temple Park Leisure Centre	0 - Hall - 054	Skirting	Timber	Refurb-demolition
Temple Park Leisure Centre	0 - Hall - 054	Boxing	Timber	Refurb-demolition
Temple Park Leisure Centre	0 - Hall - 054	Boxing Void	Non Asbestos	Refurb-demolition
Temple Park Leisure Centre	0 - Hall - 054	Window Frame	Timber	Refurb-demolition
Temple Park Leisure Centre	0 - Hall - 054	Wall Panel	Timber	Refurb-demolition
Temple Park Leisure Centre	0 - Hall - 054	Ducting	Metal	Refurb-demolition
Temple Park Leisure Centre	0 - Hall - 054	Loose Insulation	MMMF	Refurb-demolition
Temple Park Leisure Centre	0 - Hall - 054	Floor	Timber	Refurb-demolition
Temple Park Leisure Centre	0 - Hall - 054	Suspended Ceiling	Plasterboard	Refurb-demolition
Temple Park Leisure Centre	0 - Hall - 054	Door And Frame	Metal	Refurb-demolition
Temple Park Leisure Centre	0 - Hall - 054	Door And Frame	Timber	Refurb-demolition
Temple Park Leisure Centre	0 - Changing Room - 055	Downpipes	Non Asbestos	Refurb-demolition
Temple Park Leisure Centre	0 - Changing Room - 055	Skirting	Stone/Ceramic Tiles	Refurb-demolition
Temple Park Leisure Centre	0 - Changing Room - 055	Beam Cladding	Timber	Refurb-demolition
Temple Park Leisure Centre	0 - Changing Room - 055	Beams	Concrete	Refurb-demolition
Temple Park Leisure Centre	0 - Changing Room - 055	Walls	Brick Block Walls	Refurb-demolition
Temple Park Leisure Centre	0 - Changing Room - 055	Ducting	Metal	Refurb-demolition

Building	Floor - Location	Item	Material	Survey Type
Temple Park Leisure Centre	0 - Changing Room - 055	Door And Frame	Timber	Refurb-demolition
Temple Park Leisure Centre	0 - Changing Room - 055	Wall Panel	Organic	Refurb-demolition
Temple Park Leisure Centre	0 - Changing Room - 055	Floor	Concrete	Refurb-demolition
Temple Park Leisure Centre	0 - Changing Room - 055	Floor Tiles	Stone/Ceramic Tiles	Refurb-demolition
Temple Park Leisure Centre	0 - Changing Room - 055	Columns	Concrete	Refurb-demolition
Temple Park Leisure Centre	0 - Changing Room - 056	Floor	Concrete	Refurb-demolition
Temple Park Leisure Centre	0 - Changing Room - 056	Pipe Work	Metal	Refurb-demolition
Temple Park Leisure Centre	0 - Changing Room - 056	Ceiling Tiles	Organic	Refurb-demolition
Temple Park Leisure Centre	0 - Changing Room - 056	Pipe Insulation	MMMF	Refurb-demolition
Temple Park Leisure Centre	0 - Changing Room - 056	Floor Tiles	Stone/Ceramic Tiles	Refurb-demolition
Temple Park Leisure Centre	0 - Changing Room - 056	Beams	Concrete	Refurb-demolition
Temple Park Leisure Centre	0 - Changing Room - 056	Door And Frame	Timber	Refurb-demolition
Temple Park Leisure Centre	0 - Changing Room - 056	Wall Tiles	Stone/Ceramic Tiles	Refurb-demolition
Temple Park Leisure Centre	0 - Changing Room - 056	Walls	Brick Block Walls	Refurb-demolition
Temple Park Leisure Centre	0 - Changing Room - 056	Ceiling	Concrete	Refurb-demolition
Temple Park Leisure Centre	0 - Changing Room - 057	Walls	Brick Block Walls	Refurb-demolition
Temple Park Leisure Centre	0 - Changing Room - 057	Door And Frame	Timber	Refurb-demolition
Temple Park Leisure Centre	0 - Changing Room - 057	Floor Tiles	Stone/Ceramic Tiles	Refurb-demolition
Temple Park Leisure Centre	0 - Changing Room - 057	Floor	Concrete	Refurb-demolition
Temple Park Leisure Centre	0 - Changing Room - 057	Columns	Concrete	Refurb-demolition
Temple Park Leisure Centre	0 - Changing Room - 057	Mastic	Organic	Refurb-demolition
Temple Park Leisure Centre	0 - Changing Room - 057	Wall Tiles	Stone/Ceramic Tiles	Refurb-demolition
Temple Park Leisure Centre	0 - Changing Room - 057	Insulation	MMMF	Refurb-demolition
Temple Park Leisure Centre	0 - Changing Room - 057	Ceiling	Concrete	Refurb-demolition
Temple Park Leisure Centre	0 - Changing Room - 057	Boxing	Plasterboard	Refurb-demolition
Temple Park Leisure Centre	0 - Changing Room - 057	Cladding	Timber	Refurb-demolition
Temple Park Leisure Centre	0 - Changing Room - 057	Pipe Work	Non Asbestos	Refurb-demolition
Temple Park Leisure Centre	0 - Changing Room - 057	Beams	Concrete	Refurb-demolition
Temple Park Leisure Centre	0 - Changing Room - 057	Ceiling Tiles	MMMF	Refurb-demolition
Temple Park Leisure Centre	0 - Changing Room - 057	Ducting	Metal	Refurb-demolition
Temple Park Leisure Centre	0 - Changing Room - 057	Infill	Timber	Refurb-demolition

Building	Floor - Location	Item	Material	Survey Type
Temple Park Leisure Centre	0 - Lift Motor Room - 075	Ceiling Tiles	MMMF	Refurb-demolition
Temple Park Leisure Centre	0 - Lift Motor Room - 075	Ducting	Metal	Refurb-demolition
Temple Park Leisure Centre	0 - Lift Motor Room - 075	Walls	Brick Block Walls	Refurb-demolition
Temple Park Leisure Centre	0 - Lift Motor Room - 075	Plant Equipment	Non Asbestos	Refurb-demolition
Temple Park Leisure Centre	0 - Lift Motor Room - 075	Floor	Concrete	Refurb-demolition
Temple Park Leisure Centre	0 - Lift Motor Room - 075	Ceiling	Concrete	Refurb-demolition
Temple Park Leisure Centre	0 - Lift Motor Room - 075	Door And Frame	Timber	Refurb-demolition
Temple Park Leisure Centre	0 - Lift Motor Room - 075	Electrical Equipment	Non Asbestos	Refurb-demolition
Temple Park Leisure Centre	0 - Cleaner's Cupboard - 077	Pipe Insulation	Foam	Refurb-demolition
Temple Park Leisure Centre	0 - Cleaner's Cupboard - 077	Insulation	MMMF	Refurb-demolition
Temple Park Leisure Centre	0 - Cleaner's Cupboard - 077	Boxing Void	Non Asbestos	Refurb-demolition
Temple Park Leisure Centre	0 - Cleaner's Cupboard - 077	Pipe Work	Metal	Refurb-demolition
Temple Park Leisure Centre	0 - Cleaner's Cupboard - 077	Ducting	Metal	Refurb-demolition
Temple Park Leisure Centre	0 - Cleaner's Cupboard - 077	Ceiling	Concrete	Refurb-demolition
Temple Park Leisure Centre	0 - Cleaner's Cupboard - 077	Beams	Concrete	Refurb-demolition
Temple Park Leisure Centre	0 - Cleaner's Cupboard - 077	Ceiling	Concrete	Refurb-demolition
Temple Park Leisure Centre	0 - Cleaner's Cupboard - 077	Floor Tiles	Stone/Ceramic Tiles	Refurb-demolition
Temple Park Leisure Centre	0 - Cleaner's Cupboard - 077	Floor	Concrete	Refurb-demolition
Temple Park Leisure Centre	0 - Cleaner's Cupboard - 077	Door And Frame	Timber	Refurb-demolition
Temple Park Leisure Centre	0 - Cleaner's Cupboard - 077	Walls	Timber	Refurb-demolition
Temple Park Leisure Centre	0 - Cleaner's Cupboard - 077	Walls	Brick Block Walls	Refurb-demolition
Temple Park Leisure Centre	0 - Cleaner's Cupboard - 077	Ceiling Tiles	Foam	Refurb-demolition
Temple Park Leisure Centre	0 - Cleaner's Cupboard - 077	Pipe	Non Asbestos	Refurb-demolition
Temple Park Leisure Centre	0 - Corridor - 078	Walls	Brick Block Walls	Refurb-demolition
Temple Park Leisure Centre	0 - Corridor - 078	Infill	Timber	Refurb-demolition
Temple Park Leisure Centre	0 - Corridor - 078	Pipe Work	Metal	Refurb-demolition
Temple Park Leisure Centre	0 - Corridor - 078	Insulation	MMMF	Refurb-demolition
Temple Park Leisure Centre	0 - Corridor - 078	Pipe Insulation	Foam	Refurb-demolition
Temple Park Leisure Centre	0 - Corridor - 078	Beams	Concrete	Refurb-demolition
Temple Park Leisure Centre	0 - Corridor - 078	Door And Frame	Timber	Refurb-demolition
Temple Park Leisure Centre	0 - Corridor - 078	Ducting	Metal	Refurb-demolition

Building	Floor - Location	Item	Material	Survey Type
Temple Park Leisure Centre	0 - Corridor - 078	Ceiling	Concrete	Refurb-demolition
Temple Park Leisure Centre	0 - Corridor - 078	Floor	Concrete	Refurb-demolition
Temple Park Leisure Centre	0 - Corridor - 078	Floor Tiles	Stone/Ceramic Tiles	Refurb-demolition
Temple Park Leisure Centre	0 - Changing Room - 079	Ceiling Tiles	Organic	Refurb-demolition
Temple Park Leisure Centre	0 - Changing Room - 079	Beams	Concrete	Refurb-demolition
Temple Park Leisure Centre	0 - Changing Room - 079	Pipe Work	Metal	Refurb-demolition
Temple Park Leisure Centre	0 - Changing Room - 079	Pipe Insulation	MMMF	Refurb-demolition
Temple Park Leisure Centre	0 - Changing Room - 079	Floor Tiles	Stone/Ceramic Tiles	Refurb-demolition
Temple Park Leisure Centre	0 - Changing Room - 079	Door And Frame	Timber	Refurb-demolition
Temple Park Leisure Centre	0 - Changing Room - 079	Floor	Concrete	Refurb-demolition
Temple Park Leisure Centre	0 - Changing Room - 079	Wall Tiles	Stone/Ceramic Tiles	Refurb-demolition
Temple Park Leisure Centre	0 - Changing Room - 079	Walls	Brick Block Walls	Refurb-demolition
Temple Park Leisure Centre	0 - Changing Room - 079	Ceiling	Concrete	Refurb-demolition
Temple Park Leisure Centre	0 - Wc - 080	Boxing	Timber	Refurb-demolition
Temple Park Leisure Centre	0 - Wc - 080	Boxing Void	Non Asbestos	Refurb-demolition
Temple Park Leisure Centre	0 - Wc - 080	Toilet Seat	Non Asbestos	Refurb-demolition
Temple Park Leisure Centre	0 - Wc - 080	Toilet Cistern	Non Asbestos	Refurb-demolition
Temple Park Leisure Centre	0 - Wc - 080	Floor Tiles	Stone/Ceramic Tiles	Refurb-demolition
Temple Park Leisure Centre	0 - Wc - 080	Ducting	Metal	Refurb-demolition
Temple Park Leisure Centre	0 - Wc - 080	Panelling	Timber	Refurb-demolition
Temple Park Leisure Centre	0 - Wc - 080	Walls	Brick Block Walls	Refurb-demolition
Temple Park Leisure Centre	0 - Wc - 080	Mastic	Organic	Refurb-demolition
Temple Park Leisure Centre	0 - Wc - 080	Door And Frame	Timber	Refurb-demolition
Temple Park Leisure Centre	0 - Wc - 080	Pipe Insulation	MMMF	Refurb-demolition
Temple Park Leisure Centre	0 - Wc - 080	Ceiling	Concrete	Refurb-demolition
Temple Park Leisure Centre	0 - Wc - 080	Beams	Concrete	Refurb-demolition
Temple Park Leisure Centre	0 - Wc - 080	Pipe Work	Metal	Refurb-demolition
Temple Park Leisure Centre	0 - Wc - 080	Floor	Concrete	Refurb-demolition
Temple Park Leisure Centre	0 - Wc Entrance Lobby - 081	Walls	Brick Block Walls	Refurb-demolition
Temple Park Leisure Centre	0 - Wc Entrance Lobby - 081	Ceiling	Concrete	Refurb-demolition
Temple Park Leisure Centre	0 - Wc Entrance Lobby - 081	Wall Panel	Organic	Refurb-demolition

Building	Floor - Location	Item	Material	Survey Type
Temple Park Leisure Centre	0 - Wc Entrance Lobby - 081	Floor	Concrete	Refurb-demolition
Temple Park Leisure Centre	0 - Wc Entrance Lobby - 081	Ducting	Metal	Refurb-demolition
Temple Park Leisure Centre	0 - Wc Entrance Lobby - 081	Floor Tiles	Stone/Ceramic Tiles	Refurb-demolition
Temple Park Leisure Centre	0 - Wc Entrance Lobby - 081	Door And Frame	Timber	Refurb-demolition
Temple Park Leisure Centre	0 - Lobby - 082	Ceiling Tiles	MMMF	Refurb-demolition
Temple Park Leisure Centre	0 - Lobby - 082	Boxing Void	Non Asbestos	Refurb-demolition
Temple Park Leisure Centre	0 - Lobby - 082	Wall Tiles	Stone/Ceramic Tiles	Refurb-demolition
Temple Park Leisure Centre	0 - Lobby - 082	Walls	Brick Block Walls	Refurb-demolition
Temple Park Leisure Centre	0 - Lobby - 082	Beams	Concrete	Refurb-demolition
Temple Park Leisure Centre	0 - Lobby - 082	Boxing	Timber	Refurb-demolition
Temple Park Leisure Centre	0 - Lobby - 082	Ducting	Metal	Refurb-demolition
Temple Park Leisure Centre	0 - Lobby - 082	Ceiling	Concrete	Refurb-demolition
Temple Park Leisure Centre	0 - Lobby - 082	Floor	Concrete	Refurb-demolition
Temple Park Leisure Centre	0 - Lobby - 082	Door And Frame	Timber	Refurb-demolition
Temple Park Leisure Centre	0 - Lobby - 082	Pipe Insulation	MMMF	Refurb-demolition
Temple Park Leisure Centre	0 - Lobby - 082	Pipe Work	Metal	Refurb-demolition
Temple Park Leisure Centre	0 - Office - 083	Walls	Brick Block Walls	Refurb-demolition
Temple Park Leisure Centre	0 - Office - 083	Skirting	Timber	Refurb-demolition
Temple Park Leisure Centre	0 - Office - 083	Ducting	Metal	Refurb-demolition
Temple Park Leisure Centre	0 - Office - 083	Ceiling Tiles	Organic	Refurb-demolition
Temple Park Leisure Centre	0 - Office - 083	Floor Covering	Organic	Refurb-demolition
Temple Park Leisure Centre	0 - Office - 083	Ceiling	Concrete	Refurb-demolition
Temple Park Leisure Centre	0 - Office - 083	Riser Void	Non Asbestos	Refurb-demolition
Temple Park Leisure Centre	0 - Office - 083	Floor	Concrete	Refurb-demolition
Temple Park Leisure Centre	0 - Office - 083	Downpipes	Non Asbestos	Refurb-demolition
Temple Park Leisure Centre	0 - Office - 083	Beams	Concrete	Refurb-demolition
Temple Park Leisure Centre	0 - Office - 083	Door And Frame	Timber	Refurb-demolition
Temple Park Leisure Centre	0 - Office - 083	Pipe Work	Non Asbestos	Refurb-demolition
Temple Park Leisure Centre	0 - Office - 083	Floor Covering	Non Asbestos	Refurb-demolition
Temple Park Leisure Centre	0 - Office - 083	Toilet Seat	Non Asbestos	Refurb-demolition
Temple Park Leisure Centre	0 - Office - 083	Toilet Cistern	Non Asbestos	Refurb-demolition

Building	Floor - Location	Item	Material	Survey Type
Temple Park Leisure Centre	0 - Office - 083	Ceiling Tiles	MMMF	Refurb-demolition
Temple Park Leisure Centre	0 - Office - 083	Riser	Timber	Refurb-demolition
Temple Park Leisure Centre	0 - Office - 083	Pipe Work	Metal	Refurb-demolition
Temple Park Leisure Centre	0 - Changing Room - 084	Ceiling	Concrete	Refurb-demolition
Temple Park Leisure Centre	0 - Changing Room - 084	Beams	Concrete	Refurb-demolition
Temple Park Leisure Centre	0 - Changing Room - 084	Columns	Concrete	Refurb-demolition
Temple Park Leisure Centre	0 - Changing Room - 084	Cladding	Timber	Refurb-demolition
Temple Park Leisure Centre	0 - Changing Room - 084	Ducting	Metal	Refurb-demolition
Temple Park Leisure Centre	0 - Changing Room - 084	Floor Tiles	Stone/Ceramic Tiles	Refurb-demolition
Temple Park Leisure Centre	0 - Changing Room - 084	Insulation	MMMF	Refurb-demolition
Temple Park Leisure Centre	0 - Changing Room - 084	Floor	Concrete	Refurb-demolition
Temple Park Leisure Centre	0 - Changing Room - 084	Door And Frame	Timber	Refurb-demolition
Temple Park Leisure Centre	0 - Changing Room - 084	Walls	Brick Block Walls	Refurb-demolition
Temple Park Leisure Centre	0 - Changing Room - 084	Ceiling Tiles	MMMF	Refurb-demolition
Temple Park Leisure Centre	0 - Changing Room - 085	Walls	Brick Block Walls	Refurb-demolition
Temple Park Leisure Centre	0 - Changing Room - 085	Insulation	MMMF	Refurb-demolition
Temple Park Leisure Centre	0 - Changing Room - 085	Pipe Insulation	MMMF	Refurb-demolition
Temple Park Leisure Centre	0 - Changing Room - 085	Pipe Work	Metal	Refurb-demolition
Temple Park Leisure Centre	0 - Changing Room - 085	Floor Tiles	Stone/Ceramic Tiles	Refurb-demolition
Temple Park Leisure Centre	0 - Changing Room - 085	Floor	Concrete	Refurb-demolition
Temple Park Leisure Centre	0 - Changing Room - 085	Wall Tiles	Stone/Ceramic Tiles	Refurb-demolition
Temple Park Leisure Centre	0 - Changing Room - 085	Ceiling	Concrete	Refurb-demolition
Temple Park Leisure Centre	0 - Changing Room - 085	Ceiling Tiles	Organic	Refurb-demolition
Temple Park Leisure Centre	0 - Changing Room - 085	Door And Frame	Timber	Refurb-demolition
Temple Park Leisure Centre	0 - Plant Room - 086	Floor	Concrete	Refurb-demolition
Temple Park Leisure Centre	0 - Plant Room - 086	Door And Frame	Timber	Refurb-demolition
Temple Park Leisure Centre	0 - Plant Room - 086	Pipe Work	Non Asbestos	Refurb-demolition
Temple Park Leisure Centre	0 - Plant Room - 086	Pipe Work	Metal	Refurb-demolition
Temple Park Leisure Centre	0 - Plant Room - 086	Walls	Brick Block Walls	Refurb-demolition
Temple Park Leisure Centre	0 - Plant Room - 086	Ceiling	Concrete	Refurb-demolition
Temple Park Leisure Centre	0 - Changing Room - 087	Pipe Insulation	MMMF	Refurb-demolition

Building	Floor - Location	Item	Material	Survey Type
Temple Park Leisure Centre	0 - Changing Room - 087	Pipe Work	Metal	Refurb-demolition
Temple Park Leisure Centre	0 - Changing Room - 087	Floor Tiles	Stone/Ceramic Tiles	Refurb-demolition
Temple Park Leisure Centre	0 - Changing Room - 087	Floor	Concrete	Refurb-demolition
Temple Park Leisure Centre	0 - Changing Room - 087	Door And Frame	Timber	Refurb-demolition
Temple Park Leisure Centre	0 - Changing Room - 087	Insulation	MMMF	Refurb-demolition
Temple Park Leisure Centre	0 - Changing Room - 087	Walls	Brick Block Walls	Refurb-demolition
Temple Park Leisure Centre	0 - Changing Room - 087	Ceiling	Concrete	Refurb-demolition
Temple Park Leisure Centre	0 - Changing Room - 087	Ceiling Tiles	Organic	Refurb-demolition
Temple Park Leisure Centre	0 - Changing Room - 087	Wall Tiles	Stone/Ceramic Tiles	Refurb-demolition
Temple Park Leisure Centre	0 - Disabled Wc - 088	Toilet Seat	Non Asbestos	Refurb-demolition
Temple Park Leisure Centre	0 - Disabled Wc - 088	Beams	Concrete	Refurb-demolition
Temple Park Leisure Centre	0 - Disabled Wc - 088	Pipe Insulation	Foam	Refurb-demolition
Temple Park Leisure Centre	0 - Disabled Wc - 088	Ceiling	Concrete	Refurb-demolition
Temple Park Leisure Centre	0 - Disabled Wc - 088	Ceiling Tiles	Organic	Refurb-demolition
Temple Park Leisure Centre	0 - Disabled Wc - 088	Toilet Cistern	Non Asbestos	Refurb-demolition
Temple Park Leisure Centre	0 - Disabled Wc - 088	Boxing Void	Non Asbestos	Refurb-demolition
Temple Park Leisure Centre	0 - Disabled Wc - 088	Panelling	Timber	Refurb-demolition
Temple Park Leisure Centre	0 - Disabled Wc - 088	Pipe Work	Metal	Refurb-demolition
Temple Park Leisure Centre	0 - Disabled Wc - 088	Ducting	Metal	Refurb-demolition
Temple Park Leisure Centre	0 - Disabled Wc - 088	Floor Tiles	Stone/Ceramic Tiles	Refurb-demolition
Temple Park Leisure Centre	0 - Disabled Wc - 088	Floor	Concrete	Refurb-demolition
Temple Park Leisure Centre	0 - Disabled Wc - 088	Walls	Timber	Refurb-demolition
Temple Park Leisure Centre	0 - Disabled Wc - 088	Wall Tiles	Stone/Ceramic Tiles	Refurb-demolition
Temple Park Leisure Centre	0 - Disabled Wc - 088	Walls	Brick Block Walls	Refurb-demolition
Temple Park Leisure Centre	0 - Disabled Wc - 088	Insulation	MMMF	Refurb-demolition
Temple Park Leisure Centre	0 - Disabled Wc - 088	Boxing	Timber	Refurb-demolition
Temple Park Leisure Centre	0 - Disabled Wc - 089	Ducting	Metal	Refurb-demolition
Temple Park Leisure Centre	0 - Disabled Wc - 089	Walls	Brick Block Walls	Refurb-demolition
Temple Park Leisure Centre	0 - Disabled Wc - 089	Ceiling	Concrete	Refurb-demolition
Temple Park Leisure Centre	0 - Disabled Wc - 089	Wall Tiles	Stone/Ceramic Tiles	Refurb-demolition
Temple Park Leisure Centre	0 - Disabled Wc - 089	Boxing	Timber	Refurb-demolition

Building	Floor - Location	Item	Material	Survey Type
Temple Park Leisure Centre	0 - Disabled Wc - 089	Boxing Void	Non Asbestos	Refurb-demolition
Temple Park Leisure Centre	0 - Disabled Wc - 089	Toilet Seat	Non Asbestos	Refurb-demolition
Temple Park Leisure Centre	0 - Disabled Wc - 089	Beams	Concrete	Refurb-demolition
Temple Park Leisure Centre	0 - Disabled Wc - 089	Walls	Timber	Refurb-demolition
Temple Park Leisure Centre	0 - Disabled Wc - 089	Floor Tiles	Stone/Ceramic Tiles	Refurb-demolition
Temple Park Leisure Centre	0 - Disabled Wc - 089	Toilet Cistern	Non Asbestos	Refurb-demolition
Temple Park Leisure Centre	0 - Disabled Wc - 089	Floor	Concrete	Refurb-demolition
Temple Park Leisure Centre	0 - Disabled Wc - 089	Ceiling Tiles	Organic	Refurb-demolition
Temple Park Leisure Centre	0 - Changing Room - 090	Ceiling	Concrete	Refurb-demolition
Temple Park Leisure Centre	0 - Changing Room - 090	Downpipes	Non Asbestos	Refurb-demolition
Temple Park Leisure Centre	0 - Changing Room - 090	Insulation	MMMF	Refurb-demolition
Temple Park Leisure Centre	0 - Changing Room - 090	Door And Frame	Timber	Refurb-demolition
Temple Park Leisure Centre	0 - Changing Room - 090	Cladding	Timber	Refurb-demolition
Temple Park Leisure Centre	0 - Changing Room - 090	Ducting	Metal	Refurb-demolition
Temple Park Leisure Centre	0 - Changing Room - 090	Floor	Concrete	Refurb-demolition
Temple Park Leisure Centre	0 - Changing Room - 090	Infill	Timber	Refurb-demolition
Temple Park Leisure Centre	0 - Changing Room - 090	Beams	Concrete	Refurb-demolition
Temple Park Leisure Centre	0 - Changing Room - 090	Wall Tiles	Stone/Ceramic Tiles	Refurb-demolition
Temple Park Leisure Centre	0 - Changing Room - 090	Walls	Brick Block Walls	Refurb-demolition
Temple Park Leisure Centre	0 - Changing Room - 090	Walls	Timber	Refurb-demolition
Temple Park Leisure Centre	0 - Changing Room - 090	Ceiling Tiles	MMMF	Refurb-demolition
Temple Park Leisure Centre	0 - Changing Room - 090	Floor Tiles	Stone/Ceramic Tiles	Refurb-demolition
Temple Park Leisure Centre	0 - Changing Room - 090	Columns	Concrete	Refurb-demolition
Temple Park Leisure Centre	0 - Corridor - 092	Pipe Work	Metal	Refurb-demolition
Temple Park Leisure Centre	0 - Corridor - 092	Insulation	MMMF	Refurb-demolition
Temple Park Leisure Centre	0 - Corridor - 092	Pipe Insulation	MMMF	Refurb-demolition
Temple Park Leisure Centre	0 - Corridor - 092	Beams	Concrete	Refurb-demolition
Temple Park Leisure Centre	0 - Corridor - 092	Ceiling	Concrete	Refurb-demolition
Temple Park Leisure Centre	0 - Corridor - 092	Floor Tiles	Stone/Ceramic Tiles	Refurb-demolition
Temple Park Leisure Centre	0 - Corridor - 092	Columns	Brick Block Walls	Refurb-demolition
Temple Park Leisure Centre	0 - Corridor - 092	Skirting	Timber	Refurb-demolition

Building	Floor - Location	Item	Material	Survey Type
Temple Park Leisure Centre	0 - Corridor - 092	Walls	Brick Block Walls	Refurb-demolition
Temple Park Leisure Centre	0 - Corridor - 092	Door And Frame	Timber	Refurb-demolition
Temple Park Leisure Centre	0 - Corridor - 092	Mastic	Organic	Refurb-demolition
Temple Park Leisure Centre	0 - Corridor - 092	Fire Door	Metal	Refurb-demolition
Temple Park Leisure Centre	0 - Corridor - 092	Ceiling Tiles	MMMF	Refurb-demolition
Temple Park Leisure Centre	0 - Corridor - 092	Floor	Concrete	Refurb-demolition
Temple Park Leisure Centre	0 - Store - 093	Door And Frame	Metal	Refurb-demolition
Temple Park Leisure Centre	0 - Store - 093	Ceiling	Concrete	Refurb-demolition
Temple Park Leisure Centre	0 - Store - 093	Beams	Concrete	Refurb-demolition
Temple Park Leisure Centre	0 - Store - 093	Ceiling Tiles	MMMF	Refurb-demolition
Temple Park Leisure Centre	0 - Store - 093	Walls	Brick Block Walls	Refurb-demolition
Temple Park Leisure Centre	0 - Store - 093	Columns	Brick Block Walls	Refurb-demolition
Temple Park Leisure Centre	0 - Store - 093	Floor Tiles	Stone/Ceramic Tiles	Refurb-demolition
Temple Park Leisure Centre	0 - Store - 093	Floor	Concrete	Refurb-demolition
Temple Park Leisure Centre	0 - Cellar - 094	Beams	Concrete	Refurb-demolition
Temple Park Leisure Centre	0 - Cellar - 094	Ceiling	Concrete	Refurb-demolition
Temple Park Leisure Centre	0 - Cellar - 094	Ceiling Tiles	MMMF	Refurb-demolition
Temple Park Leisure Centre	0 - Cellar - 094	Walls	Brick Block Walls	Refurb-demolition
Temple Park Leisure Centre	0 - Cellar - 094	Columns	Concrete	Refurb-demolition
Temple Park Leisure Centre	0 - Cellar - 094	Pipe Insulation	Foam	Refurb-demolition
Temple Park Leisure Centre	0 - Cellar - 094	Sink	Metal	Refurb-demolition
Temple Park Leisure Centre	0 - Cellar - 094	Panel	Timber	Refurb-demolition
Temple Park Leisure Centre	0 - Cellar - 094	Floor	Concrete	Refurb-demolition
Temple Park Leisure Centre	0 - Cellar - 094	Door And Frame	Timber	Refurb-demolition
Temple Park Leisure Centre	0 - Cellar - 094	Pipe	Metal	Refurb-demolition
Temple Park Leisure Centre	0 - Cellar - 094	Chiller Unit	Non Asbestos	Refurb-demolition
Temple Park Leisure Centre	0 - Cellar - 094	Electrical Equipment	Non Asbestos	Refurb-demolition
Temple Park Leisure Centre	0 - Stock Room - 095	Pipe Insulation	MMMF	Refurb-demolition
Temple Park Leisure Centre	0 - Stock Room - 095	Beams	Concrete	Refurb-demolition
Temple Park Leisure Centre	0 - Stock Room - 095	Pipe Insulation	Foam	Refurb-demolition
Temple Park Leisure Centre	0 - Stock Room - 095	Door And Frame	Timber	Refurb-demolition

Building	Floor - Location	Item	Material	Survey Type
Temple Park Leisure Centre	0 - Stock Room - 095	Walls	Brick Block Walls	Refurb-demolition
Temple Park Leisure Centre	0 - Stock Room - 095	Columns	Concrete	Refurb-demolition
Temple Park Leisure Centre	0 - Stock Room - 095	Ceiling Tiles	MMMF	Refurb-demolition
Temple Park Leisure Centre	0 - Stock Room - 095	Floor	Concrete	Refurb-demolition
Temple Park Leisure Centre	0 - Stock Room - 095	Electrical Equipment	Non Asbestos	Refurb-demolition
Temple Park Leisure Centre	0 - Stock Room - 095	Pipe Work	Metal	Refurb-demolition
Temple Park Leisure Centre	0 - Stock Room - 095	Ceiling	Concrete	Refurb-demolition
Temple Park Leisure Centre	0 - Stock Room - 095	Downpipes	Non Asbestos	Refurb-demolition
Temple Park Leisure Centre	0 - Electrical Cupboard - 096	Insulation	MMMF	Refurb-demolition
Temple Park Leisure Centre	0 - Electrical Cupboard - 096	Panel	Organic	Refurb-demolition
Temple Park Leisure Centre	0 - Electrical Cupboard - 096	Ceiling	Concrete	Refurb-demolition
Temple Park Leisure Centre	0 - Electrical Cupboard - 096	Columns	Concrete	Refurb-demolition
Temple Park Leisure Centre	0 - Electrical Cupboard - 096	Walls	Brick Block Walls	Refurb-demolition
Temple Park Leisure Centre	0 - Electrical Cupboard - 096	Door And Frame	Timber	Refurb-demolition
Temple Park Leisure Centre	0 - Electrical Cupboard - 096	Walls	Plasterboard	Refurb-demolition
Temple Park Leisure Centre	0 - Electrical Cupboard - 096	Downpipes	Non Asbestos	Refurb-demolition
Temple Park Leisure Centre	0 - Electrical Cupboard - 096	Floor	Concrete	Refurb-demolition
Temple Park Leisure Centre	0 - Electrical Cupboard - 096	Electrical Equipment	Non Asbestos	Refurb-demolition
Temple Park Leisure Centre	0 - Store Room - 097	Walls	Brick Block Walls	Refurb-demolition
Temple Park Leisure Centre	0 - Store Room - 097	Door And Frame	Timber	Refurb-demolition
Temple Park Leisure Centre	0 - Store Room - 097	Beams	Concrete	Refurb-demolition
Temple Park Leisure Centre	0 - Store Room - 097	Ceiling	Concrete	Refurb-demolition
Temple Park Leisure Centre	0 - Store Room - 097	Ducting	Metal	Refurb-demolition
Temple Park Leisure Centre	0 - Store Room - 097	Electrics	Non Asbestos	Refurb-demolition
Temple Park Leisure Centre	0 - Store Room - 097	Floor	Concrete	Refurb-demolition
Temple Park Leisure Centre	0 - Stairwell - 098	Door And Frame	Metal	Refurb-demolition
Temple Park Leisure Centre	0 - Stairwell - 098	Fire Door	Metal	Refurb-demolition
Temple Park Leisure Centre	0 - Stairwell - 098	Roof	Metal	Refurb-demolition
Temple Park Leisure Centre	0 - Stairwell - 098	Ceiling Tiles	MMMF	Refurb-demolition
Temple Park Leisure Centre	0 - Stairwell - 098	Beams	Concrete	Refurb-demolition
Temple Park Leisure Centre	0 - Stairwell - 098	Floor	Concrete	Refurb-demolition

Building	Floor - Location	Item	Material	Survey Type
Temple Park Leisure Centre	0 - Stairwell - 098	Stair Nosing	Organic	Refurb-demolition
Temple Park Leisure Centre	0 - Stairwell - 098	Beams	Metal	Refurb-demolition
Temple Park Leisure Centre	0 - Stairwell - 098	Beams	Metal	Refurb-demolition
Temple Park Leisure Centre	0 - Stairwell - 098	Columns	Concrete	Refurb-demolition
Temple Park Leisure Centre	0 - Stairwell - 098	Beams	Metal	Refurb-demolition
Temple Park Leisure Centre	0 - Stairwell - 098	Walls	Non Asbestos	Refurb-demolition
Temple Park Leisure Centre	0 - Stairwell - 098	Stairs	Concrete	Refurb-demolition
Temple Park Leisure Centre	0 - Stairwell - 098	Floor	Concrete	Refurb-demolition
Temple Park Leisure Centre	0 - Stairwell - 098	Ceiling Tiles	Plasterboard	Refurb-demolition
Temple Park Leisure Centre	0 - Stairwell - 098	Walls	Brick Block Walls	Refurb-demolition
Temple Park Leisure Centre	0 - Stairwell - 098	Door And Frame	Timber	Refurb-demolition
Temple Park Leisure Centre	0 - Stairwell - 098	Bulkhead	Organic	Refurb-demolition
Temple Park Leisure Centre	0 - Stairwell - 098	Ceiling Tiles	Organic	Refurb-demolition
Temple Park Leisure Centre	0 - Stairwell - 098	Floor Covering	Organic	Refurb-demolition
Temple Park Leisure Centre	0 - Plant Room - 099	Walls	Brick Block Walls	Refurb-demolition
Temple Park Leisure Centre	0 - Plant Room - 099	Floor	Concrete	Refurb-demolition
Temple Park Leisure Centre	0 - Plant Room - 099	Pipe Work	Non Asbestos	Refurb-demolition
Temple Park Leisure Centre	0 - Plant Room - 099	Floor	Timber	Refurb-demolition
Temple Park Leisure Centre	0 - Plant Room - 099	Pipe Work	Metal	Refurb-demolition
Temple Park Leisure Centre	0 - Plant Room - 099	Door And Frame	Timber	Refurb-demolition
Temple Park Leisure Centre	1 - Reception - 032	Infill	Timber	Refurb-demolition
Temple Park Leisure Centre	1 - Reception - 032	Infill	Non Asbestos	Refurb-demolition
Temple Park Leisure Centre	1 - Reception - 032	Ceiling Tiles	MMMF	Refurb-demolition
Temple Park Leisure Centre	1 - Reception - 032	Kitchen Units	Timber	Refurb-demolition
Temple Park Leisure Centre	1 - Reception - 032	Floor Covering	Non Asbestos	Refurb-demolition
Temple Park Leisure Centre	1 - Reception - 032	Pipe	Non Asbestos	Refurb-demolition
Temple Park Leisure Centre	1 - Reception - 032	Beading	Non Asbestos	Refurb-demolition
Temple Park Leisure Centre	1 - Reception - 032	Cladding	Timber	Refurb-demolition
Temple Park Leisure Centre	1 - Reception - 032	Pipe Work	Metal	Refurb-demolition
Temple Park Leisure Centre	1 - Reception - 032	Pipe Insulation	Foam	Refurb-demolition
Temple Park Leisure Centre	1 - Reception - 032	Beams	Metal	Refurb-demolition

Building	Floor - Location	Item	Material	Survey Type
Temple Park Leisure Centre	1 - Reception - 032	Roof	Timber	Refurb-demolition
Temple Park Leisure Centre	1 - Reception - 032	Ducting	Metal	Refurb-demolition
Temple Park Leisure Centre	1 - Reception - 032	Beams	Timber	Refurb-demolition
Temple Park Leisure Centre	1 - Reception - 032	Boxing Void	Non Asbestos	Refurb-demolition
Temple Park Leisure Centre	1 - Reception - 032	Ducting Insulation	MMMF	Refurb-demolition
Temple Park Leisure Centre	1 - Reception - 032	Floor	Concrete	Refurb-demolition
Temple Park Leisure Centre	1 - Reception - 032	Window Frame	Timber	Refurb-demolition
Temple Park Leisure Centre	1 - Reception - 032	Walls	Brick Block Walls	Refurb-demolition
Temple Park Leisure Centre	1 - Reception - 032	Boxing	Timber	Refurb-demolition
Temple Park Leisure Centre	1 - Reception - 032	Columns	Metal	Refurb-demolition
Temple Park Leisure Centre	1 - Reception - 032	Air Conditioning Unit	Non Asbestos	Refurb-demolition
Temple Park Leisure Centre	1 - Reception - 032	Door And Frame	Timber	Refurb-demolition
Temple Park Leisure Centre	1 - Reception - 032	Window Frame	Metal	Refurb-demolition
Temple Park Leisure Centre	1 - Entrance Lobby - 033	Heating Unit	Non Asbestos	Refurb-demolition
Temple Park Leisure Centre	1 - Entrance Lobby - 033	Stairs	Metal	Refurb-demolition
Temple Park Leisure Centre	1 - Entrance Lobby - 033	Boxing	Timber	Refurb-demolition
Temple Park Leisure Centre	1 - Entrance Lobby - 033	Ducting Insulation	Metal	Refurb-demolition
Temple Park Leisure Centre	1 - Entrance Lobby - 033	Ducting	Metal	Refurb-demolition
Temple Park Leisure Centre	1 - Entrance Lobby - 033	Columns	Concrete	Refurb-demolition
Temple Park Leisure Centre	1 - Entrance Lobby - 033	Beams	Concrete	Refurb-demolition
Temple Park Leisure Centre	1 - Entrance Lobby - 033	Beams	Metal	Refurb-demolition
Temple Park Leisure Centre	1 - Entrance Lobby - 033	Ceiling	Metal	Refurb-demolition
Temple Park Leisure Centre	1 - Entrance Lobby - 033	Heating Unit	Metal	Refurb-demolition
Temple Park Leisure Centre	1 - Entrance Lobby - 033	Downpipes	Non Asbestos	Refurb-demolition
Temple Park Leisure Centre	1 - Entrance Lobby - 033	Columns	Metal	Refurb-demolition
Temple Park Leisure Centre	1 - Entrance Lobby - 033	Panelling	Timber	Refurb-demolition
Temple Park Leisure Centre	1 - Entrance Lobby - 033	Canopy	Glass	Refurb-demolition
Temple Park Leisure Centre	1 - Entrance Lobby - 033	Canopy	Metal	Refurb-demolition
Temple Park Leisure Centre	1 - Entrance Lobby - 033	Boxing Void	Non Asbestos	Refurb-demolition
Temple Park Leisure Centre	1 - Entrance Lobby - 033	Floor Tiles	Stone/Ceramic Tiles	Refurb-demolition
Temple Park Leisure Centre	1 - Entrance Lobby - 033	Bulkhead	Plasterboard	Refurb-demolition

Building	Floor - Location	Item	Material	Survey Type
Temple Park Leisure Centre	1 - Entrance Lobby - 033	Mastic	Organic	Refurb-demolition
Temple Park Leisure Centre	1 - Entrance Lobby - 033	Infill	Organic	Refurb-demolition
Temple Park Leisure Centre	1 - Entrance Lobby - 033	Roof	Timber	Refurb-demolition
Temple Park Leisure Centre	1 - Entrance Lobby - 033	Door	Glass	Refurb-demolition
Temple Park Leisure Centre	1 - Entrance Lobby - 033	Door And Frame	Timber	Refurb-demolition
Temple Park Leisure Centre	1 - Entrance Lobby - 033	Door And Frame	Metal	Refurb-demolition
Temple Park Leisure Centre	1 - Entrance Lobby - 033	Window Frame	Metal	Refurb-demolition
Temple Park Leisure Centre	1 - Entrance Lobby - 033	Pipe Insulation	Foam	Refurb-demolition
Temple Park Leisure Centre	1 - Entrance Lobby - 033	Pipe Insulation	MMMF	Refurb-demolition
Temple Park Leisure Centre	1 - Entrance Lobby - 033	Pipe Work	Metal	Refurb-demolition
Temple Park Leisure Centre	1 - Entrance Lobby - 033	Fire Break	MMMF	Refurb-demolition
Temple Park Leisure Centre	1 - Entrance Lobby - 033	Air Conditioning Unit	Non Asbestos	Refurb-demolition
Temple Park Leisure Centre	1 - Entrance Lobby - 033	Riser Void	Non Asbestos	Refurb-demolition
Temple Park Leisure Centre	1 - Entrance Lobby - 033	Riser	Timber	Refurb-demolition
Temple Park Leisure Centre	1 - Entrance Lobby - 033	Skirting	Timber	Refurb-demolition
Temple Park Leisure Centre	1 - Entrance Lobby - 033	Walls	Plasterboard	Refurb-demolition
Temple Park Leisure Centre	1 - Entrance Lobby - 033	Floor	Concrete	Refurb-demolition
Temple Park Leisure Centre	1 - Entrance Lobby - 033	Walls	Brick Block Walls	Refurb-demolition
Temple Park Leisure Centre	1 - Office - 034	Pipe Work	Metal	Refurb-demolition
Temple Park Leisure Centre	1 - Office - 034	Ceiling	Plasterboard	Refurb-demolition
Temple Park Leisure Centre	1 - Office - 034	Walls	Brick Block Walls	Refurb-demolition
Temple Park Leisure Centre	1 - Office - 034	Door And Frame	Timber	Refurb-demolition
Temple Park Leisure Centre	1 - Office - 034	Ducting	Metal	Refurb-demolition
Temple Park Leisure Centre	1 - Office - 034	Pipe	Non Asbestos	Refurb-demolition
Temple Park Leisure Centre	1 - Office - 034	Floor	Concrete	Refurb-demolition
Temple Park Leisure Centre	1 - Office - 034	Pipe Insulation	Foam	Refurb-demolition
Temple Park Leisure Centre	1 - Office - 034	Electrical Equipment	Non Asbestos	Refurb-demolition
Temple Park Leisure Centre	1 - Office - 034	Roof	Timber	Refurb-demolition
Temple Park Leisure Centre	1 - Office - 034	Air Conditioning Unit	Non Asbestos	Refurb-demolition
Temple Park Leisure Centre	1 - Stairwell - 035	Window Frame	Timber	Refurb-demolition
Temple Park Leisure Centre	1 - Stairwell - 035	Boxing	Metal	Refurb-demolition

Building	Floor - Location	Item	Material	Survey Type
Temple Park Leisure Centre	1 - Stairwell - 035	Stairs	Concrete	Refurb-demolition
Temple Park Leisure Centre	1 - Stairwell - 035	Boxing Void	Non Asbestos	Refurb-demolition
Temple Park Leisure Centre	1 - Stairwell - 035	Skirting	Timber	Refurb-demolition
Temple Park Leisure Centre	1 - Stairwell - 035	Infill	Metal	Refurb-demolition
Temple Park Leisure Centre	1 - Stairwell - 035	Columns	Concrete	Refurb-demolition
Temple Park Leisure Centre	1 - Stairwell - 035	Beams	Concrete	Refurb-demolition
Temple Park Leisure Centre	1 - Stairwell - 035	Sky Light	Glass	Refurb-demolition
Temple Park Leisure Centre	1 - Stairwell - 035	Floor Tiles	Stone/Ceramic Tiles	Refurb-demolition
Temple Park Leisure Centre	1 - Stairwell - 035	Walls	Brick Block Walls	Refurb-demolition
Temple Park Leisure Centre	1 - Stairwell - 035	Sky Light	Metal	Refurb-demolition
Temple Park Leisure Centre	1 - Cafe - 036	Boxing Void	Non Asbestos	Refurb-demolition
Temple Park Leisure Centre	1 - Cafe - 036	Ceiling	Concrete	Refurb-demolition
Temple Park Leisure Centre	1 - Cafe - 036	Beams	Concrete	Refurb-demolition
Temple Park Leisure Centre	1 - Cafe - 036	Bulkhead	Plasterboard	Refurb-demolition
Temple Park Leisure Centre	1 - Cafe - 036	Columns	Concrete	Refurb-demolition
Temple Park Leisure Centre	1 - Cafe - 036	Ducting	Metal	Refurb-demolition
Temple Park Leisure Centre	1 - Cafe - 036	Ducting Insulation	MMMF	Refurb-demolition
Temple Park Leisure Centre	1 - Cafe - 036	Pipe Insulation	MMMF	Refurb-demolition
Temple Park Leisure Centre	1 - Cafe - 036	Infill	Timber	Refurb-demolition
Temple Park Leisure Centre	1 - Cafe - 036	Pipe Work	Metal	Refurb-demolition
Temple Park Leisure Centre	1 - Cafe - 036	Window Frame	Timber	Refurb-demolition
Temple Park Leisure Centre	1 - Cafe - 036	Roof	Metal	Refurb-demolition
Temple Park Leisure Centre	1 - Cafe - 036	Wall Panel	Timber	Refurb-demolition
Temple Park Leisure Centre	1 - Cafe - 036	Downpipes	Non Asbestos	Refurb-demolition
Temple Park Leisure Centre	1 - Cafe - 036	Door And Frame	Timber	Refurb-demolition
Temple Park Leisure Centre	1 - Cafe - 036	Wall Tiles	Stone/Ceramic Tiles	Refurb-demolition
Temple Park Leisure Centre	1 - Cafe - 036	Skirting	Timber	Refurb-demolition
Temple Park Leisure Centre	1 - Cafe - 036	Floor	Concrete	Refurb-demolition
Temple Park Leisure Centre	1 - Cafe - 036	Wall Panel	Organic	Refurb-demolition
Temple Park Leisure Centre	1 - Cafe - 036	Walls	Brick Block Walls	Refurb-demolition
Temple Park Leisure Centre	1 - Cafe - 036	Wall Panel	Timber	Refurb-demolition

Building	Floor - Location	Item	Material	Survey Type
Temple Park Leisure Centre	1 - Cafe - 036	Kitchen Units	Timber	Refurb-demolition
Temple Park Leisure Centre	1 - Cafe - 036	Panel	Organic	Refurb-demolition
Temple Park Leisure Centre	1 - Cafe - 036	Floor Tiles	Stone/Ceramic Tiles	Refurb-demolition
Temple Park Leisure Centre	1 - Cafe - 036	Columns	Brick Block Walls	Refurb-demolition
Temple Park Leisure Centre	1 - Cafe - 036	Ceiling Tiles	MMMF	Refurb-demolition
Temple Park Leisure Centre	1 - Cafe - 036	Ceiling Tiles	Organic	Refurb-demolition
Temple Park Leisure Centre	1 - Cafe - 036	Boxing	Organic	Refurb-demolition
Temple Park Leisure Centre	1 - Store - 037	Ceiling Tiles	MMMF	Refurb-demolition
Temple Park Leisure Centre	1 - Store - 037	Roof	Metal	Refurb-demolition
Temple Park Leisure Centre	1 - Store - 037	Pipe Work	Metal	Refurb-demolition
Temple Park Leisure Centre	1 - Store - 037	Floor	Concrete	Refurb-demolition
Temple Park Leisure Centre	1 - Store - 037	Riser Void	Non Asbestos	Refurb-demolition
Temple Park Leisure Centre	1 - Store - 037	Pipe Insulation	MMMF	Refurb-demolition
Temple Park Leisure Centre	1 - Store - 037	Columns	Concrete	Refurb-demolition
Temple Park Leisure Centre	1 - Store - 037	Ducting Insulation	MMMF	Refurb-demolition
Temple Park Leisure Centre	1 - Store - 037	Ducting	Metal	Refurb-demolition
Temple Park Leisure Centre	1 - Store - 037	Walls	Brick Block Walls	Refurb-demolition
Temple Park Leisure Centre	1 - Store - 037	Walls	Brick Block Walls	Refurb-demolition
Temple Park Leisure Centre	1 - Store - 037	Downpipes	Non Asbestos	Refurb-demolition
Temple Park Leisure Centre	1 - Store - 037	Riser	Timber	Refurb-demolition
Temple Park Leisure Centre	1 - Store - 037	Walls	Timber	Refurb-demolition
Temple Park Leisure Centre	1 - Store - 037	Door And Frame	Timber	Refurb-demolition
Temple Park Leisure Centre	1 - Store - 037	Skirting	Timber	Refurb-demolition
Temple Park Leisure Centre	1 - Store - 037	Beams	Metal	Refurb-demolition
Temple Park Leisure Centre	1 - Store - 037	Insulation	MMMF	Refurb-demolition
Temple Park Leisure Centre	1 - Corridor - 038	Boxing	Timber	Refurb-demolition
Temple Park Leisure Centre	1 - Corridor - 038	Boxing Void	Non Asbestos	Refurb-demolition
Temple Park Leisure Centre	1 - Corridor - 038	Downpipes	Non Asbestos	Refurb-demolition
Temple Park Leisure Centre	1 - Corridor - 038	Ceiling	Plasterboard	Refurb-demolition
Temple Park Leisure Centre	1 - Corridor - 038	Walls	Plasterboard	Refurb-demolition
Temple Park Leisure Centre	1 - Corridor - 038	Pipe Work	Metal	Refurb-demolition

Building	Floor - Location	Item	Material	Survey Type
Temple Park Leisure Centre	1 - Corridor - 038	Mastic	Organic	Refurb-demolition
Temple Park Leisure Centre	1 - Corridor - 038	Skirting	Timber	Refurb-demolition
Temple Park Leisure Centre	1 - Corridor - 038	Beams	Concrete	Refurb-demolition
Temple Park Leisure Centre	1 - Corridor - 038	Wall Cavity	Non Asbestos	Refurb-demolition
Temple Park Leisure Centre	1 - Corridor - 038	Beams	Metal	Refurb-demolition
Temple Park Leisure Centre	1 - Corridor - 038	Roof	Metal	Refurb-demolition
Temple Park Leisure Centre	1 - Corridor - 038	Ducting	Metal	Refurb-demolition
Temple Park Leisure Centre	1 - Corridor - 038	Window Frame	Timber	Refurb-demolition
Temple Park Leisure Centre	1 - Corridor - 038	Door And Frame	Timber	Refurb-demolition
Temple Park Leisure Centre	1 - Corridor - 038	Walls	Glass	Refurb-demolition
Temple Park Leisure Centre	1 - Corridor - 038	Walls	Brick Block Walls	Refurb-demolition
Temple Park Leisure Centre	1 - Corridor - 038	Roof	Metal	Refurb-demolition
Temple Park Leisure Centre	1 - Corridor - 038	Floor	Concrete	Refurb-demolition
Temple Park Leisure Centre	1 - Office - 039	Walls	Brick Block Walls	Refurb-demolition
Temple Park Leisure Centre	1 - Office - 039	Walls	Plasterboard	Refurb-demolition
Temple Park Leisure Centre	1 - Office - 039	Wall Cavity	Non Asbestos	Refurb-demolition
Temple Park Leisure Centre	1 - Office - 039	Skirting	Non Asbestos	Refurb-demolition
Temple Park Leisure Centre	1 - Office - 039	Floor	Timber	Refurb-demolition
Temple Park Leisure Centre	1 - Office - 039	Floor	Concrete	Refurb-demolition
Temple Park Leisure Centre	1 - Office - 039	Door	Timber	Refurb-demolition
Temple Park Leisure Centre	1 - Office - 040	Sink Pad	Organic	Refurb-demolition
Temple Park Leisure Centre	1 - Office - 040	Walls	Plasterboard	Refurb-demolition
Temple Park Leisure Centre	1 - Office - 040	Floor	Concrete	Refurb-demolition
Temple Park Leisure Centre	1 - Office - 040	Floor Covering	Non Asbestos	Refurb-demolition
Temple Park Leisure Centre	1 - Office - 040	Door	Timber	Refurb-demolition
Temple Park Leisure Centre	1 - Office - 040	Walls	Brick Block Walls	Refurb-demolition
Temple Park Leisure Centre	1 - Office - 040	Skirting	Non Asbestos	Refurb-demolition
Temple Park Leisure Centre	1 - Office - 040	Wall Cavity	Non Asbestos	Refurb-demolition
Temple Park Leisure Centre	1 - Office - 040	Sink	Metal	Refurb-demolition
Temple Park Leisure Centre	1 - Office - 041	Skirting	Non Asbestos	Refurb-demolition
Temple Park Leisure Centre	1 - Office - 041	Wall Cavity	Non Asbestos	Refurb-demolition

Building	Floor - Location	Item	Material	Survey Type
Temple Park Leisure Centre	1 - Office - 041	Walls	Brick Block Walls	Refurb-demolition
Temple Park Leisure Centre	1 - Office - 041	Floor Covering	Timber	Refurb-demolition
Temple Park Leisure Centre	1 - Office - 041	Floor	Concrete	Refurb-demolition
Temple Park Leisure Centre	1 - Office - 041	Walls	Plasterboard	Refurb-demolition
Temple Park Leisure Centre	1 - Office - 041	Door	Timber	Refurb-demolition
Temple Park Leisure Centre	1 - Office - 041	Skirting	Timber	Refurb-demolition
Temple Park Leisure Centre	1 - Hall - 042	Window Frame	Timber	Refurb-demolition
Temple Park Leisure Centre	1 - Hall - 042	Downpipes	Non Asbestos	Refurb-demolition
Temple Park Leisure Centre	1 - Hall - 042	Ducting	Metal	Refurb-demolition
Temple Park Leisure Centre	1 - Hall - 042	Roof	Metal	Refurb-demolition
Temple Park Leisure Centre	1 - Hall - 042	Ceiling Tiles	MMMF	Refurb-demolition
Temple Park Leisure Centre	1 - Hall - 042	Ducting Insulation	MMMF	Refurb-demolition
Temple Park Leisure Centre	1 - Hall - 042	Skirting	Timber	Refurb-demolition
Temple Park Leisure Centre	1 - Hall - 042	Wall Cavity	Non Asbestos	Refurb-demolition
Temple Park Leisure Centre	1 - Hall - 042	Door And Frame	Timber	Refurb-demolition
Temple Park Leisure Centre	1 - Hall - 042	Floor Covering	Non Asbestos	Refurb-demolition
Temple Park Leisure Centre	1 - Hall - 042	Floor	Concrete	Refurb-demolition
Temple Park Leisure Centre	1 - Hall - 042	Walls	Brick Block Walls	Refurb-demolition
Temple Park Leisure Centre	1 - Hall - 042	Columns	Concrete	Refurb-demolition
Temple Park Leisure Centre	1 - Hall - 042	Walls	Plasterboard	Refurb-demolition
Temple Park Leisure Centre	1 - Hall - 042	Beams	Metal	Refurb-demolition
Temple Park Leisure Centre	1 - Hall - 042	Beams	Concrete	Refurb-demolition
Temple Park Leisure Centre	1 - Hall - 043	Floor Covering	Non Asbestos	Refurb-demolition
Temple Park Leisure Centre	1 - Hall - 043	Walls	Brick Block Walls	Refurb-demolition
Temple Park Leisure Centre	1 - Hall - 043	Window Frame	Timber	Refurb-demolition
Temple Park Leisure Centre	1 - Hall - 043	Door And Frame	Timber	Refurb-demolition
Temple Park Leisure Centre	1 - Hall - 043	Floor	Concrete	Refurb-demolition
Temple Park Leisure Centre	1 - Hall - 043	Raised Floor	Timber	Refurb-demolition
Temple Park Leisure Centre	1 - Hall - 043	Walls	Plasterboard	Refurb-demolition
Temple Park Leisure Centre	1 - Hall - 043	Roof	Metal	Refurb-demolition
Temple Park Leisure Centre	1 - Hall - 043	Stair Nosing	Non Asbestos	Refurb-demolition

Building	Floor - Location	Item	Material	Survey Type
Temple Park Leisure Centre	1 - Hall - 043	Beams	Metal	Refurb-demolition
Temple Park Leisure Centre	1 - Hall - 043	Columns	Metal	Refurb-demolition
Temple Park Leisure Centre	1 - Hall - 043	Ducting	Metal	Refurb-demolition
Temple Park Leisure Centre	1 - Hall - 043	Columns	Concrete	Refurb-demolition
Temple Park Leisure Centre	1 - Hall - 043	Beams	Concrete	Refurb-demolition
Temple Park Leisure Centre	1 - Hall - 043	Panel	Timber	Refurb-demolition
Temple Park Leisure Centre	1 - Hall - 043	Stairs	Metal	Refurb-demolition
Temple Park Leisure Centre	1 - Hall - 043	Infill	Timber	Refurb-demolition
Temple Park Leisure Centre	1 - Hall - 044	Columns	Concrete	Refurb-demolition
Temple Park Leisure Centre	1 - Hall - 044	Panel	Timber	Refurb-demolition
Temple Park Leisure Centre	1 - Hall - 044	Pipe	Metal	Refurb-demolition
Temple Park Leisure Centre	1 - Hall - 044	Pipe Insulation	MMMF	Refurb-demolition
Temple Park Leisure Centre	1 - Hall - 044	Beams	Metal	Refurb-demolition
Temple Park Leisure Centre	1 - Hall - 044	Floor	Concrete	Refurb-demolition
Temple Park Leisure Centre	1 - Hall - 044	Ducting	Metal	Refurb-demolition
Temple Park Leisure Centre	1 - Hall - 044	Wall Panel	Timber	Refurb-demolition
Temple Park Leisure Centre	1 - Hall - 044	Beams	Concrete	Refurb-demolition
Temple Park Leisure Centre	1 - Hall - 044	Walls	Glass	Refurb-demolition
Temple Park Leisure Centre	1 - Hall - 044	Walls	Brick Block Walls	Refurb-demolition
Temple Park Leisure Centre	1 - Hall - 044	Raised Floor	Timber	Refurb-demolition
Temple Park Leisure Centre	1 - Hall - 044	Roof	Metal	Refurb-demolition
Temple Park Leisure Centre	1 - Hall - 045	Beams	Concrete	Refurb-demolition
Temple Park Leisure Centre	1 - Hall - 045	Walls	Glass	Refurb-demolition
Temple Park Leisure Centre	1 - Hall - 045	Raised Floor	Timber	Refurb-demolition
Temple Park Leisure Centre	1 - Hall - 045	Walls	Brick Block Walls	Refurb-demolition
Temple Park Leisure Centre	1 - Hall - 045	Wall Panel	Timber	Refurb-demolition
Temple Park Leisure Centre	1 - Hall - 045	Beams	Metal	Refurb-demolition
Temple Park Leisure Centre	1 - Hall - 045	Roof	Metal	Refurb-demolition
Temple Park Leisure Centre	1 - Hall - 045	Columns	Concrete	Refurb-demolition
Temple Park Leisure Centre	1 - Hall - 045	Ducting	Metal	Refurb-demolition
Temple Park Leisure Centre	1 - Hall - 045	Pipe Insulation	MMMF	Refurb-demolition

Building	Floor - Location	Item	Material	Survey Type
Temple Park Leisure Centre	1 - Hall - 045	Pipe	Metal	Refurb-demolition
Temple Park Leisure Centre	1 - Hall - 045	Panel	Timber	Refurb-demolition
Temple Park Leisure Centre	1 - Hall - 045	Floor	Concrete	Refurb-demolition
Temple Park Leisure Centre	1 - Hall - 046	Beams	Concrete	Refurb-demolition
Temple Park Leisure Centre	1 - Hall - 046	Beams	Metal	Refurb-demolition
Temple Park Leisure Centre	1 - Hall - 046	Wall Panel	Timber	Refurb-demolition
Temple Park Leisure Centre	1 - Hall - 046	Roof	Metal	Refurb-demolition
Temple Park Leisure Centre	1 - Hall - 046	Walls	Brick Block Walls	Refurb-demolition
Temple Park Leisure Centre	1 - Hall - 046	Floor	Concrete	Refurb-demolition
Temple Park Leisure Centre	1 - Hall - 046	Walls	Glass	Refurb-demolition
Temple Park Leisure Centre	1 - Hall - 046	Columns	Concrete	Refurb-demolition
Temple Park Leisure Centre	1 - Hall - 046	Ducting	Metal	Refurb-demolition
Temple Park Leisure Centre	1 - Hall - 046	Pipe Insulation	MMMF	Refurb-demolition
Temple Park Leisure Centre	1 - Hall - 046	Pipe	Metal	Refurb-demolition
Temple Park Leisure Centre	1 - Hall - 046	Panel	Timber	Refurb-demolition
Temple Park Leisure Centre	1 - Hall - 046	Raised Floor	Timber	Refurb-demolition
Temple Park Leisure Centre	1 - Landing - 047	Floor	Concrete	Refurb-demolition
Temple Park Leisure Centre	1 - Landing - 047	Door And Frame	Timber	Refurb-demolition
Temple Park Leisure Centre	1 - Landing - 047	Skirting	Timber	Refurb-demolition
Temple Park Leisure Centre	1 - Landing - 047	Ceiling Tiles	Organic	Refurb-demolition
Temple Park Leisure Centre	1 - Landing - 047	Ceiling	Metal	Refurb-demolition
Temple Park Leisure Centre	1 - Landing - 047	Walls	Brick Block Walls	Refurb-demolition
Temple Park Leisure Centre	1 - Landing - 047	Beams	Metal	Refurb-demolition
Temple Park Leisure Centre	1 - Landing - 047	Columns	Concrete	Refurb-demolition
Temple Park Leisure Centre	1 - Landing - 047	Columns	Metal	Refurb-demolition
Temple Park Leisure Centre	1 - Landing - 047	Roof	Metal	Refurb-demolition
Temple Park Leisure Centre	1 - Landing - 047	Walls	Non Asbestos	Refurb-demolition
Temple Park Leisure Centre	1 - Cupboard - 048	Floor	Concrete	Refurb-demolition
Temple Park Leisure Centre	1 - Cupboard - 048	Walls	Brick Block Walls	Refurb-demolition
Temple Park Leisure Centre	1 - Cupboard - 048	Pipe	Non Asbestos	Refurb-demolition
Temple Park Leisure Centre	1 - Cupboard - 048	Pipe Insulation	MMMF	Refurb-demolition

Building	Floor - Location	Item	Material	Survey Type
Temple Park Leisure Centre	1 - Cupboard - 048	Beams	Concrete	Refurb-demolition
Temple Park Leisure Centre	1 - Cupboard - 048	Columns	Brick Block Walls	Refurb-demolition
Temple Park Leisure Centre	1 - Cupboard - 048	Boxing	Timber	Refurb-demolition
Temple Park Leisure Centre	1 - Cupboard - 048	Boxing Void	Non Asbestos	Refurb-demolition
Temple Park Leisure Centre	1 - Cupboard - 048	Skirting	Timber	Refurb-demolition
Temple Park Leisure Centre	1 - Cupboard - 048	Beading	Timber	Refurb-demolition
Temple Park Leisure Centre	1 - Cupboard - 048	Beams	Metal	Refurb-demolition
Temple Park Leisure Centre	1 - Cupboard - 048	Roof	Metal	Refurb-demolition
Temple Park Leisure Centre	1 - Cupboard - 048	Ceiling Tiles	Organic	Refurb-demolition
Temple Park Leisure Centre	1 - Cupboard - 048	Floor Covering	Organic	Refurb-demolition
Temple Park Leisure Centre	1 - Cupboard - 048	Door And Frame	Timber	Refurb-demolition
Temple Park Leisure Centre	1 - Corridor - 049	Boxing	Organic	Refurb-demolition
Temple Park Leisure Centre	1 - Corridor - 049	Floor Tiles	Stone/Ceramic Tiles	Refurb-demolition
Temple Park Leisure Centre	1 - Corridor - 049	Floor	Concrete	Refurb-demolition
Temple Park Leisure Centre	1 - Corridor - 049	Columns	Concrete	Refurb-demolition
Temple Park Leisure Centre	1 - Corridor - 049	Walls	Brick Block Walls	Refurb-demolition
Temple Park Leisure Centre	1 - Corridor - 049	Beams	Concrete	Refurb-demolition
Temple Park Leisure Centre	1 - Corridor - 049	Ceiling	Concrete	Refurb-demolition
Temple Park Leisure Centre	1 - Corridor - 049	Fire Blanket	MMMF	Refurb-demolition
Temple Park Leisure Centre	1 - Corridor - 049	Ducting Insulation	MMMF	Refurb-demolition
Temple Park Leisure Centre	1 - Corridor - 049	Ducting	Metal	Refurb-demolition
Temple Park Leisure Centre	1 - Corridor - 049	Ceiling Tiles	MMMF	Refurb-demolition
Temple Park Leisure Centre	1 - Corridor - 049	Wall Panel	Timber	Refurb-demolition
Temple Park Leisure Centre	1 - Corridor - 049	Signage	Non Asbestos	Refurb-demolition
Temple Park Leisure Centre	1 - Corridor - 049	Boxing Void	Non Asbestos	Refurb-demolition
Temple Park Leisure Centre	1 - Corridor - 049	Boxing	Timber	Refurb-demolition
Temple Park Leisure Centre	1 - Corridor - 049	Skirting	Timber	Refurb-demolition
Temple Park Leisure Centre	1 - Corridor - 049	Door And Frame	Timber	Refurb-demolition
Temple Park Leisure Centre	1 - Corridor - 049	Door And Frame	Metal	Refurb-demolition
Temple Park Leisure Centre	1 - Kitchen - 050	Ducting Insulation	MMMF	Refurb-demolition
Temple Park Leisure Centre	1 - Kitchen - 050	Ducting	Metal	Refurb-demolition

Building	Floor - Location	Item	Material	Survey Type
Temple Park Leisure Centre	1 - Kitchen - 050	Columns	Concrete	Refurb-demolition
Temple Park Leisure Centre	1 - Kitchen - 050	Beams	Concrete	Refurb-demolition
Temple Park Leisure Centre	1 - Kitchen - 050	Ceiling	Concrete	Refurb-demolition
Temple Park Leisure Centre	1 - Kitchen - 050	Kitchen Units	Metal	Refurb-demolition
Temple Park Leisure Centre	1 - Kitchen - 050	Ceiling Tiles	Foam	Refurb-demolition
Temple Park Leisure Centre	1 - Kitchen - 050	Sink	Metal	Refurb-demolition
Temple Park Leisure Centre	1 - Kitchen - 050	Door And Frame	Timber	Refurb-demolition
Temple Park Leisure Centre	1 - Kitchen - 050	Floor	Stone/Ceramic Tiles	Refurb-demolition
Temple Park Leisure Centre	1 - Kitchen - 050	Downpipes	Non Asbestos	Refurb-demolition
Temple Park Leisure Centre	1 - Kitchen - 050	Walls	Brick Block Walls	Refurb-demolition
Temple Park Leisure Centre	1 - Kitchen - 050	Roof Felt	Organic	Refurb-demolition
Temple Park Leisure Centre	1 - Kitchen - 050	Fire Break	MMMF	Refurb-demolition
Temple Park Leisure Centre	1 - Kitchen - 050	Pipe Insulation	MMMF	Refurb-demolition
Temple Park Leisure Centre	1 - Kitchen - 050	Sink	Organic	Refurb-demolition
Temple Park Leisure Centre	1 - Kitchen - 050	Pipe Work	Metal	Refurb-demolition
Temple Park Leisure Centre	1 - Kitchen - 050	Wall Tiles	Stone/Ceramic Tiles	Refurb-demolition
Temple Park Leisure Centre	1 - Canteen - 051	Ducting	Metal	Refurb-demolition
Temple Park Leisure Centre	1 - Canteen - 051	Boxing Void	Non Asbestos	Refurb-demolition
Temple Park Leisure Centre	1 - Canteen - 051	Boxing	Metal	Refurb-demolition
Temple Park Leisure Centre	1 - Canteen - 051	Walls	Brick Block Walls	Refurb-demolition
Temple Park Leisure Centre	1 - Canteen - 051	Ceiling	Concrete	Refurb-demolition
Temple Park Leisure Centre	1 - Canteen - 051	Beams	Concrete	Refurb-demolition
Temple Park Leisure Centre	1 - Canteen - 051	Ceiling Tiles	MMMF	Refurb-demolition
Temple Park Leisure Centre	1 - Canteen - 051	Ducting Insulation	MMMF	Refurb-demolition
Temple Park Leisure Centre	1 - Canteen - 051	Fire Break	MMMF	Refurb-demolition
Temple Park Leisure Centre	1 - Canteen - 051	Wall Tiles	Stone/Ceramic Tiles	Refurb-demolition
Temple Park Leisure Centre	1 - Canteen - 051	Door And Frame	Timber	Refurb-demolition
Temple Park Leisure Centre	1 - Canteen - 051	Riser	Timber	Refurb-demolition
Temple Park Leisure Centre	1 - Canteen - 051	Riser Void	Non Asbestos	Refurb-demolition
Temple Park Leisure Centre	1 - Canteen - 051	Kitchen Units	Timber	Refurb-demolition
Temple Park Leisure Centre	1 - Canteen - 051	Columns	Concrete	Refurb-demolition

Building	Floor - Location	Item	Material	Survey Type
Temple Park Leisure Centre	1 - Male Wc - 052	Ceiling	Concrete	Refurb-demolition
Temple Park Leisure Centre	1 - Male Wc - 052	Walls	Brick Block Walls	Refurb-demolition
Temple Park Leisure Centre	1 - Male Wc - 052	Wall Panel	Timber	Refurb-demolition
Temple Park Leisure Centre	1 - Male Wc - 052	Pipe Insulation	MMMF	Refurb-demolition
Temple Park Leisure Centre	1 - Male Wc - 052	Downpipes	Non Asbestos	Refurb-demolition
Temple Park Leisure Centre	1 - Male Wc - 052	Panelling	Timber	Refurb-demolition
Temple Park Leisure Centre	1 - Male Wc - 052	Insulation	MMMF	Refurb-demolition
Temple Park Leisure Centre	1 - Male Wc - 052	Ducting Insulation	MMMF	Refurb-demolition
Temple Park Leisure Centre	1 - Male Wc - 052	Ducting	Metal	Refurb-demolition
Temple Park Leisure Centre	1 - Male Wc - 052	Beams	Concrete	Refurb-demolition
Temple Park Leisure Centre	1 - Male Wc - 052	Columns	Concrete	Refurb-demolition
Temple Park Leisure Centre	1 - Male Wc - 052	Toilet Seat	Non Asbestos	Refurb-demolition
Temple Park Leisure Centre	1 - Male Wc - 052	Boxing	Timber	Refurb-demolition
Temple Park Leisure Centre	1 - Male Wc - 052	Door And Frame	Timber	Refurb-demolition
Temple Park Leisure Centre	1 - Male Wc - 052	Floor	Concrete	Refurb-demolition
Temple Park Leisure Centre	1 - Male Wc - 052	Floor Tiles	Stone/Ceramic Tiles	Refurb-demolition
Temple Park Leisure Centre	1 - Male Wc - 052	Toilet Cistern	Non Asbestos	Refurb-demolition
Temple Park Leisure Centre	1 - Male Wc - 052	Boxing Void	Non Asbestos	Refurb-demolition
Temple Park Leisure Centre	1 - Disabled Wc - 053	Door And Frame	Timber	Refurb-demolition
Temple Park Leisure Centre	1 - Disabled Wc - 053	Ceiling	Concrete	Refurb-demolition
Temple Park Leisure Centre	1 - Disabled Wc - 053	Toilet Cistern	Non Asbestos	Refurb-demolition
Temple Park Leisure Centre	1 - Disabled Wc - 053	Walls	Brick Block Walls	Refurb-demolition
Temple Park Leisure Centre	1 - Disabled Wc - 053	Beams	Concrete	Refurb-demolition
Temple Park Leisure Centre	1 - Disabled Wc - 053	Ducting	Metal	Refurb-demolition
Temple Park Leisure Centre	1 - Disabled Wc - 053	Ducting Insulation	MMMF	Refurb-demolition
Temple Park Leisure Centre	1 - Disabled Wc - 053	Insulation	MMMF	Refurb-demolition
Temple Park Leisure Centre	1 - Disabled Wc - 053	Downpipes	Non Asbestos	Refurb-demolition
Temple Park Leisure Centre	1 - Disabled Wc - 053	Toilet Seat	Non Asbestos	Refurb-demolition
Temple Park Leisure Centre	1 - Disabled Wc - 053	Pipe Work	Metal	Refurb-demolition
Temple Park Leisure Centre	1 - Disabled Wc - 053	Wall Panel	Timber	Refurb-demolition
Temple Park Leisure Centre	1 - Disabled Wc - 053	Floor	Concrete	Refurb-demolition

Building	Floor - Location	Item	Material	Survey Type
Temple Park Leisure Centre	1 - Disabled Wc - 053	Floor Tiles	Stone/Ceramic Tiles	Refurb-demolition
Temple Park Leisure Centre	1 - Disabled Wc - 053	Pipe Insulation	MMMF	Refurb-demolition
Temple Park Leisure Centre	1 - Disabled Wc - 053	Columns	Concrete	Refurb-demolition
Temple Park Leisure Centre	1 - Disabled Wc - 053	Pipe Work	Non Asbestos	Refurb-demolition
Temple Park Leisure Centre	1 - Female Wc - 054	Columns	Concrete	Refurb-demolition
Temple Park Leisure Centre	1 - Female Wc - 054	Toilet Cistern	Non Asbestos	Refurb-demolition
Temple Park Leisure Centre	1 - Female Wc - 054	Toilet Seat	Non Asbestos	Refurb-demolition
Temple Park Leisure Centre	1 - Female Wc - 054	Floor	Concrete	Refurb-demolition
Temple Park Leisure Centre	1 - Female Wc - 054	Floor Tiles	Stone/Ceramic Tiles	Refurb-demolition
Temple Park Leisure Centre	1 - Female Wc - 054	Wall Panel	Timber	Refurb-demolition
Temple Park Leisure Centre	1 - Female Wc - 054	Ceiling Tiles	Plasterboard	Refurb-demolition
Temple Park Leisure Centre	1 - Female Wc - 054	Beams	Concrete	Refurb-demolition
Temple Park Leisure Centre	1 - Female Wc - 054	Boxing Void	Non Asbestos	Refurb-demolition
Temple Park Leisure Centre	1 - Female Wc - 054	Walls	Brick Block Walls	Refurb-demolition
Temple Park Leisure Centre	1 - Female Wc - 054	Ceiling	Concrete	Refurb-demolition
Temple Park Leisure Centre	1 - Female Wc - 054	Ducting	Metal	Refurb-demolition
Temple Park Leisure Centre	1 - Female Wc - 054	Ducting Insulation	MMMF	Refurb-demolition
Temple Park Leisure Centre	1 - Female Wc - 054	Insulation	MMMF	Refurb-demolition
Temple Park Leisure Centre	1 - Female Wc - 054	Downpipes	Non Asbestos	Refurb-demolition
Temple Park Leisure Centre	1 - Female Wc - 054	Pipe Insulation	Foam	Refurb-demolition
Temple Park Leisure Centre	1 - Female Wc - 054	Panelling	Timber	Refurb-demolition
Temple Park Leisure Centre	1 - Female Wc - 054	Boxing	Timber	Refurb-demolition
Temple Park Leisure Centre	1 - Female Wc - 054	Door And Frame	Timber	Refurb-demolition
Temple Park Leisure Centre	1 - Female Wc - 054	Pipe Work	Metal	Refurb-demolition
Temple Park Leisure Centre	1 - Stock Room - 055	Beams	Concrete	Refurb-demolition
Temple Park Leisure Centre	1 - Stock Room - 055	Wall Tiles	Brick Block Walls	Refurb-demolition
Temple Park Leisure Centre	1 - Stock Room - 055	Downpipes	Non Asbestos	Refurb-demolition
Temple Park Leisure Centre	1 - Stock Room - 055	Ducting Insulation	MMMF	Refurb-demolition
Temple Park Leisure Centre	1 - Stock Room - 055	Columns	Concrete	Refurb-demolition
Temple Park Leisure Centre	1 - Stock Room - 055	Ceiling	Concrete	Refurb-demolition
Temple Park Leisure Centre	1 - Stock Room - 055	Ceiling Tiles	Foam	Refurb-demolition

Building	Floor - Location	Item	Material	Survey Type
Temple Park Leisure Centre	1 - Stock Room - 055	Pipe Work	Metal	Refurb-demolition
Temple Park Leisure Centre	1 - Stock Room - 055	Floor Tiles	Stone/Ceramic Tiles	Refurb-demolition
Temple Park Leisure Centre	1 - Stock Room - 055	Floor	Concrete	Refurb-demolition
Temple Park Leisure Centre	1 - Stock Room - 055	Door And Frame	Timber	Refurb-demolition
Temple Park Leisure Centre	1 - Stock Room - 055	Ducting	Metal	Refurb-demolition
Temple Park Leisure Centre	1 - Utility Room - 056	Beams	Concrete	Refurb-demolition
Temple Park Leisure Centre	1 - Utility Room - 056	Ducting	Metal	Refurb-demolition
Temple Park Leisure Centre	1 - Utility Room - 056	Ducting Insulation	MMMF	Refurb-demolition
Temple Park Leisure Centre	1 - Utility Room - 056	Downpipes	Non Asbestos	Refurb-demolition
Temple Park Leisure Centre	1 - Utility Room - 056	Sink	Metal	Refurb-demolition
Temple Park Leisure Centre	1 - Utility Room - 056	Ceiling	Concrete	Refurb-demolition
Temple Park Leisure Centre	1 - Utility Room - 056	Columns	Concrete	Refurb-demolition
Temple Park Leisure Centre	1 - Utility Room - 056	Floor Covering	Non Asbestos	Refurb-demolition
Temple Park Leisure Centre	1 - Utility Room - 056	Door And Frame	Timber	Refurb-demolition
Temple Park Leisure Centre	1 - Utility Room - 056	Skirting	Timber	Refurb-demolition
Temple Park Leisure Centre	1 - Utility Room - 056	Walls	Brick Block Walls	Refurb-demolition
Temple Park Leisure Centre	1 - Utility Room - 056	Ceiling Tiles	Foam	Refurb-demolition
Temple Park Leisure Centre	1 - Utility Room - 056	Floor	Concrete	Refurb-demolition
Temple Park Leisure Centre	1 - Electrical Cupboard - 057	Walls	Brick Block Walls	Refurb-demolition
Temple Park Leisure Centre	1 - Electrical Cupboard - 057	Floor	Concrete	Refurb-demolition
Temple Park Leisure Centre	1 - Electrical Cupboard - 057	Door And Frame	Timber	Refurb-demolition
Temple Park Leisure Centre	1 - Electrical Cupboard - 057	Electrical Equipment	Non Asbestos	Refurb-demolition
Temple Park Leisure Centre	1 - Electrical Cupboard - 057	Ceiling	Concrete	Refurb-demolition
Temple Park Leisure Centre	1 - Electrical Cupboard - 057	Beams	Concrete	Refurb-demolition
Temple Park Leisure Centre	1 - Electrical Cupboard - 057	Panel	Organic	Refurb-demolition
Temple Park Leisure Centre	1 - Electrical Cupboard - 057	Downpipes	Non Asbestos	Refurb-demolition
Temple Park Leisure Centre	1 - Electrical Cupboard - 057	Insulation	MMMF	Refurb-demolition
Temple Park Leisure Centre	1 - Electrical Cupboard - 057	Floor Tiles	Stone/Ceramic Tiles	Refurb-demolition
Temple Park Leisure Centre	1 - Kitchen - 058	Chiller Unit	Non Asbestos	Refurb-demolition
Temple Park Leisure Centre	1 - Kitchen - 058	Window Frame	Timber	Refurb-demolition
Temple Park Leisure Centre	1 - Kitchen - 058	Pipe	Metal	Refurb-demolition

Building	Floor - Location	Item	Material	Survey Type
Temple Park Leisure Centre	1 - Kitchen - 058	Floor Tiles	Stone/Ceramic Tiles	Refurb-demolition
Temple Park Leisure Centre	1 - Kitchen - 058	Floor	Concrete	Refurb-demolition
Temple Park Leisure Centre	1 - Kitchen - 058	Door And Frame	Timber	Refurb-demolition
Temple Park Leisure Centre	1 - Kitchen - 058	Wall Tiles	Stone/Ceramic Tiles	Refurb-demolition
Temple Park Leisure Centre	1 - Kitchen - 058	Pipe Insulation	MMMF	Refurb-demolition
Temple Park Leisure Centre	1 - Kitchen - 058	Ceiling	Concrete	Refurb-demolition
Temple Park Leisure Centre	1 - Kitchen - 058	Panelling	Metal	Refurb-demolition
Temple Park Leisure Centre	1 - Kitchen - 058	Walls	Brick Block Walls	Refurb-demolition
Temple Park Leisure Centre	1 - Kitchen - 058	Ceiling Tiles	Foam	Refurb-demolition
Temple Park Leisure Centre	1 - Kitchen - 058	Insulation	MMMF	Refurb-demolition
Temple Park Leisure Centre	1 - Kitchen - 058	Fire Break	MMMF	Refurb-demolition
Temple Park Leisure Centre	1 - Kitchen - 058	Sink	Metal	Refurb-demolition
Temple Park Leisure Centre	1 - Kitchen - 058	Kitchen Units	Metal	Refurb-demolition
Temple Park Leisure Centre	1 - Kitchen - 058	Pipe	Non Asbestos	Refurb-demolition
Temple Park Leisure Centre	1 - Kitchen - 058	Beams	Concrete	Refurb-demolition
Temple Park Leisure Centre	1 - Kitchen - 058	Columns	Concrete	Refurb-demolition
Temple Park Leisure Centre	1 - Kitchen - 058	Ducting	Metal	Refurb-demolition
Temple Park Leisure Centre	1 - Kitchen - 058	Sink	Organic	Refurb-demolition
Temple Park Leisure Centre	1 - Kitchen - 058	Ducting Insulation	MMMF	Refurb-demolition
Temple Park Leisure Centre	1 - Kitchen - 058	Electrical Equipment	Non Asbestos	Refurb-demolition
Temple Park Leisure Centre	1 - Kitchen - 058	Downpipes	Non Asbestos	Refurb-demolition
Temple Park Leisure Centre	1 - Office - 059	Columns	Concrete	Refurb-demolition
Temple Park Leisure Centre	1 - Office - 059	Ceiling	Concrete	Refurb-demolition
Temple Park Leisure Centre	1 - Office - 059	Ceiling Tiles	Foam	Refurb-demolition
Temple Park Leisure Centre	1 - Office - 059	Door And Frame	Timber	Refurb-demolition
Temple Park Leisure Centre	1 - Office - 059	Skirting	Timber	Refurb-demolition
Temple Park Leisure Centre	1 - Office - 059	Window Frame	Timber	Refurb-demolition
Temple Park Leisure Centre	1 - Office - 059	Floor	Concrete	Refurb-demolition
Temple Park Leisure Centre	1 - Office - 059	Floor Covering	Non Asbestos	Refurb-demolition
Temple Park Leisure Centre	1 - Office - 059	Walls	Brick Block Walls	Refurb-demolition
Temple Park Leisure Centre	1 - Office - 059	Beams	Concrete	Refurb-demolition

Building	Floor - Location	Item	Material	Survey Type
Temple Park Leisure Centre	1 - Office - 059	Ducting	Metal	Refurb-demolition
Temple Park Leisure Centre	1 - Office - 059	Ducting Insulation	MMMF	Refurb-demolition
Temple Park Leisure Centre	1 - Office - 059	Downpipes	Non Asbestos	Refurb-demolition
Temple Park Leisure Centre	1 - Bar - 060	Panelling	Timber	Refurb-demolition
Temple Park Leisure Centre	1 - Bar - 060	Ceiling Tiles	MMMF	Refurb-demolition
Temple Park Leisure Centre	1 - Bar - 060	Sink	Bitumen/Felts	Refurb-demolition
Temple Park Leisure Centre	1 - Bar - 060	Ceiling Tiles	Organic	Refurb-demolition
Temple Park Leisure Centre	1 - Bar - 060	Ceiling	Concrete	Refurb-demolition
Temple Park Leisure Centre	1 - Bar - 060	Downpipes	Non Asbestos	Refurb-demolition
Temple Park Leisure Centre	1 - Bar - 060	Beams	Concrete	Refurb-demolition
Temple Park Leisure Centre	1 - Bar - 060	Walls	Brick Block Walls	Refurb-demolition
Temple Park Leisure Centre	1 - Bar - 060	Ducting	Metal	Refurb-demolition
Temple Park Leisure Centre	1 - Bar - 060	Ducting Insulation	MMMF	Refurb-demolition
Temple Park Leisure Centre	1 - Bar - 060	Boxing	Timber	Refurb-demolition
Temple Park Leisure Centre	1 - Bar - 060	Pipe Work	Non Asbestos	Refurb-demolition
Temple Park Leisure Centre	1 - Bar - 060	Pipe Work	Metal	Refurb-demolition
Temple Park Leisure Centre	1 - Bar - 060	Stairs	Timber	Refurb-demolition
Temple Park Leisure Centre	1 - Bar - 060	Stair Nosing	Non Asbestos	Refurb-demolition
Temple Park Leisure Centre	1 - Bar - 060	Sink	Metal	Refurb-demolition
Temple Park Leisure Centre	1 - Bar - 060	Floor	Concrete	Refurb-demolition
Temple Park Leisure Centre	1 - Bar - 060	Floor Tiles	Stone/Ceramic Tiles	Refurb-demolition
Temple Park Leisure Centre	1 - Bar - 060	Floor Covering	Non Asbestos	Refurb-demolition
Temple Park Leisure Centre	1 - Bar - 060	Door And Frame	Metal	Refurb-demolition
Temple Park Leisure Centre	1 - Bar - 060	Columns	Concrete	Refurb-demolition
Temple Park Leisure Centre	1 - Bar - 060	Floor	Timber	Refurb-demolition
Temple Park Leisure Centre	1 - Bar - 060	Boxing Void	Non Asbestos	Refurb-demolition
Temple Park Leisure Centre	1 - Bar - 060	Loose Insulation	MMMF	Refurb-demolition
Temple Park Leisure Centre	1 - Bar - 060	Ducting	Metal	Refurb-demolition
Temple Park Leisure Centre	1 - Bar - 060	Walls	Brick Block Walls	Refurb-demolition
Temple Park Leisure Centre	1 - Bar - 060	Ceiling	Concrete	Refurb-demolition
Temple Park Leisure Centre	1 - Bar - 060	Wall Cavity	Non Asbestos	Refurb-demolition

Building	Floor - Location	Item	Material	Survey Type
Temple Park Leisure Centre	1 - Bar - 060	Ceiling	Plasterboard	Refurb-demolition
Temple Park Leisure Centre	1 - Bar - 060	Floor Covering	Non Asbestos	Refurb-demolition
Temple Park Leisure Centre	1 - Bar - 060	Floor	Concrete	Refurb-demolition
Temple Park Leisure Centre	1 - Bar - 060	Window Frame	Metal	Refurb-demolition
Temple Park Leisure Centre	1 - Bar - 060	Door And Frame	Timber	Refurb-demolition
Temple Park Leisure Centre	1 - Bar - 060	Suspended Ceiling	MMMF	Refurb-demolition
Temple Park Leisure Centre	1 - Bar - 060	Stair Nosing	Non Asbestos	Refurb-demolition
Temple Park Leisure Centre	1 - Bar - 060	Cladding	Plasterboard	Refurb-demolition
Temple Park Leisure Centre	1 - Bar - 060	Rain Water Goods	Non Asbestos	Refurb-demolition
Temple Park Leisure Centre	1 - Bar - 060	Columns	Concrete	Refurb-demolition
Temple Park Leisure Centre	1 - Bar - 060	Beams	Concrete	Refurb-demolition
Temple Park Leisure Centre	1 - Gymnasium - 061	Ducting	Metal	Refurb-demolition
Temple Park Leisure Centre	1 - Gymnasium - 061	Columns	Concrete	Refurb-demolition
Temple Park Leisure Centre	1 - Gymnasium - 061	Ducting Insulation	MMMF	Refurb-demolition
Temple Park Leisure Centre	1 - Gymnasium - 061	Fire Break	MMMF	Refurb-demolition
Temple Park Leisure Centre	1 - Gymnasium - 061	Roof	Metal	Refurb-demolition
Temple Park Leisure Centre	1 - Gymnasium - 061	Floor Tiles	Stone/Ceramic Tiles	Refurb-demolition
Temple Park Leisure Centre	1 - Gymnasium - 061	Skirting	Timber	Refurb-demolition
Temple Park Leisure Centre	1 - Gymnasium - 061	Ceiling Tiles	MMMF	Refurb-demolition
Temple Park Leisure Centre	1 - Gymnasium - 061	Walls	Brick Block Walls	Refurb-demolition
Temple Park Leisure Centre	1 - Gymnasium - 061	Beams	Metal	Refurb-demolition
Temple Park Leisure Centre	1 - Gymnasium - 061	Raised Floor	Timber	Refurb-demolition
Temple Park Leisure Centre	1 - Gymnasium - 061	Stair Nosing	Non Asbestos	Refurb-demolition
Temple Park Leisure Centre	1 - Gymnasium - 061	Door And Frame	Timber	Refurb-demolition
Temple Park Leisure Centre	1 - Gymnasium - 061	Window Frame	Timber	Refurb-demolition
Temple Park Leisure Centre	1 - Gymnasium - 061	Floor Covering	Non Asbestos	Refurb-demolition
Temple Park Leisure Centre	1 - Gymnasium - 061	Floor	Concrete	Refurb-demolition
Temple Park Leisure Centre	1 - Landing - 062	Columns	Concrete	Refurb-demolition
Temple Park Leisure Centre	1 - Landing - 062	Floor	Concrete	Refurb-demolition
Temple Park Leisure Centre	1 - Landing - 062	Beams	Metal	Refurb-demolition
Temple Park Leisure Centre	1 - Landing - 062	Walls	Non Asbestos	Refurb-demolition

Building	Floor - Location	Item	Material	Survey Type
Temple Park Leisure Centre	1 - Landing - 062	Roof	Metal	Refurb-demolition
Temple Park Leisure Centre	1 - Landing - 062	Door And Frame	Timber	Refurb-demolition
Temple Park Leisure Centre	1 - Landing - 062	Ceiling Tiles	Plasterboard	Refurb-demolition
Temple Park Leisure Centre	1 - Landing - 062	Walls	Brick Block Walls	Refurb-demolition
Temple Park Leisure Centre	1 - Landing - 062	Ceiling Void	Organic	Refurb-demolition
Temple Park Leisure Centre	1 - Landing - 062	Floor Covering	Organic	Refurb-demolition
Temple Park Leisure Centre	1 - Office - 063	Walls	Timber	Refurb-demolition
Temple Park Leisure Centre	1 - Office - 063	Beams	Concrete	Refurb-demolition
Temple Park Leisure Centre	1 - Office - 063	Beam Cladding	Plasterboard	Refurb-demolition
Temple Park Leisure Centre	1 - Office - 063	Window Frame	Timber	Refurb-demolition
Temple Park Leisure Centre	1 - Office - 063	Door And Frame	Timber	Refurb-demolition
Temple Park Leisure Centre	1 - Office - 063	Walls	Brick Block Walls	Refurb-demolition
Temple Park Leisure Centre	1 - Office - 063	Floor Covering	Non Asbestos	Refurb-demolition
Temple Park Leisure Centre	1 - Office - 063	Skirting	Timber	Refurb-demolition
Temple Park Leisure Centre	1 - Office - 063	Ceiling	Plasterboard	Refurb-demolition
Temple Park Leisure Centre	1 - Office - 063	Electrical Equipment	Non Asbestos	Refurb-demolition
Temple Park Leisure Centre	1 - Office - 063	Floor	Concrete	Refurb-demolition
Temple Park Leisure Centre	1 - Corridor - 064	Pipe Insulation	MMMF	Refurb-demolition
Temple Park Leisure Centre	1 - Corridor - 064	Beams	Concrete	Refurb-demolition
Temple Park Leisure Centre	1 - Corridor - 064	Mastic	Organic	Refurb-demolition
Temple Park Leisure Centre	1 - Corridor - 064	Pipe Work	Metal	Refurb-demolition
Temple Park Leisure Centre	1 - Corridor - 064	Door And Frame	Metal	Refurb-demolition
Temple Park Leisure Centre	1 - Corridor - 064	Wall Panel	Organic	Refurb-demolition
Temple Park Leisure Centre	1 - Corridor - 064	Walls	Brick Block Walls	Refurb-demolition
Temple Park Leisure Centre	1 - Corridor - 064	Floor	Concrete	Refurb-demolition
Temple Park Leisure Centre	1 - Corridor - 064	Ducting Insulation	MMMF	Refurb-demolition
Temple Park Leisure Centre	1 - Corridor - 064	Door And Frame	Timber	Refurb-demolition
Temple Park Leisure Centre	1 - Corridor - 064	Ceiling Tiles	MMMF	Refurb-demolition
Temple Park Leisure Centre	1 - Corridor - 064	Walls	Timber	Refurb-demolition
Temple Park Leisure Centre	1 - Corridor - 064	Skirting	Timber	Refurb-demolition
Temple Park Leisure Centre	1 - Corridor - 064	Infill	Timber	Refurb-demolition

Building	Floor - Location	Item	Material	Survey Type
Temple Park Leisure Centre	1 - Corridor - 064	Beading	Timber	Refurb-demolition
Temple Park Leisure Centre	1 - Corridor - 064	Ceiling	Concrete	Refurb-demolition
Temple Park Leisure Centre	1 - Corridor - 064	Ducting	Metal	Refurb-demolition
Temple Park Leisure Centre	1 - Corridor - 064	Floor Tiles	Stone/Ceramic Tiles	Refurb-demolition
Temple Park Leisure Centre	1 - Electrical Switchroom - 081A	Ducting	Metal	Refurb-demolition
Temple Park Leisure Centre	1 - Electrical Switchroom - 081A	Downpipes	Non Asbestos	Refurb-demolition
Temple Park Leisure Centre	1 - Electrical Switchroom - 081A	Beams	Concrete	Refurb-demolition
Temple Park Leisure Centre	1 - Electrical Switchroom - 081A	Floor Panel	Metal	Refurb-demolition
Temple Park Leisure Centre	1 - Electrical Switchroom - 081A	Ceiling	Plasterboard	Refurb-demolition
Temple Park Leisure Centre	1 - Electrical Switchroom - 081A	Walls	Brick Block Walls	Refurb-demolition
Temple Park Leisure Centre	1 - Electrical Switchroom - 081A	Columns	Concrete	Refurb-demolition
Temple Park Leisure Centre	1 - Electrical Switchroom - 081A	Ducting Insulation	MMMF	Refurb-demolition
Temple Park Leisure Centre	1 - Electrical Switchroom - 081A	Door And Frame	Timber	Refurb-demolition
Temple Park Leisure Centre	1 - Electrical Switchroom - 081A	Insulation	MMMF	Refurb-demolition
Temple Park Leisure Centre	1 - Electrical Switchroom - 081A	Electrical Equipment	Non Asbestos	Refurb-demolition
Temple Park Leisure Centre	1 - Electrical Switchroom - 081A	Floor	Concrete	Refurb-demolition
Temple Park Leisure Centre	1 - Electrical Switchroom - 081A	Floor Tiles	Stone/Ceramic Tiles	Refurb-demolition
Temple Park Leisure Centre	1 - Electrical Switchroom - 081A	Ceiling Tiles	MMMF	Refurb-demolition
Temple Park Leisure Centre	1 - Electrical Switchroom - 081A	Walls	Plasterboard	Refurb-demolition
Temple Park Leisure Centre	2 - Tank Room - 001	Walls	Brick Block Walls	Refurb-demolition
Temple Park Leisure Centre	2 - Tank Room - 001	Pipe Insulation	Organic	Refurb-demolition
Temple Park Leisure Centre	2 - Tank Room - 001	Floor	Organic	Refurb-demolition
Temple Park Leisure Centre	2 - Tank Room - 001	Debris	Organic	Refurb-demolition
Temple Park Leisure Centre	2 - Tank Room - 001	Door And Frame	Timber	Refurb-demolition
Temple Park Leisure Centre	2 - Tank Room - 001	Columns	Organic	Refurb-demolition
Temple Park Leisure Centre	2 - Tank Room - 001	Pipe Insulation	Organic	Refurb-demolition
Temple Park Leisure Centre	2 - Tank Room - 001	Cladding	MMMF	Refurb-demolition
Temple Park Leisure Centre	2 - Tank Room - 001	Wall Cavity	Non Asbestos	Refurb-demolition
Temple Park Leisure Centre	2 - Tank Room - 001	Walls	Plasterboard	Refurb-demolition
Temple Park Leisure Centre	2 - Tank Room - 001	Air Conditioning Unit	Non Asbestos	Refurb-demolition
Temple Park Leisure Centre	2 - Tank Room - 001	Wall Insulation	Foam	Refurb-demolition

Building	Floor - Location	Item	Material	Survey Type
Temple Park Leisure Centre	2 - Tank Room - 001	Rain Water Goods	Non Asbestos	Refurb-demolition
Temple Park Leisure Centre	2 - Tank Room - 001	Roof	Metal	Refurb-demolition
Temple Park Leisure Centre	2 - Tank Room - 001	Columns	Metal	Refurb-demolition
Temple Park Leisure Centre	2 - Tank Room - 001	Beams	Metal	Refurb-demolition
Temple Park Leisure Centre	2 - Tank Room - 001	Water Tank	Metal	Refurb-demolition
Temple Park Leisure Centre	2 - Tank Room - 001	Plant Equipment	Non Asbestos	Refurb-demolition
Temple Park Leisure Centre	2 - Tank Room - 001	Floor	Concrete	Refurb-demolition
Temple Park Leisure Centre	2 - Tank Room - 001	Pipe Work	Metal	Refurb-demolition
Temple Park Leisure Centre	2 - Tank Room - 001	Door And Frame	Metal	Refurb-demolition
Temple Park Leisure Centre	2 - Tank Room - 001	Electrics	Metal	Refurb-demolition
Temple Park Leisure Centre	2 - Tank Room - 001	Ducting	Metal	Refurb-demolition
Temple Park Leisure Centre	2 - Tank Room - 001	Loose Insulation	MMMF	Refurb-demolition
Temple Park Leisure Centre	99 - External - 501	Roof Soffit	Non Asbestos	Refurb-demolition
Temple Park Leisure Centre	99 - External - 501	Columns	Organic	Refurb-demolition
Temple Park Leisure Centre	99 - External - 501	Promenade Tiles	Organic	Refurb-demolition
Temple Park Leisure Centre	99 - External - 501	Pipe Work	Metal	Refurb-demolition
Temple Park Leisure Centre	99 - External - 501	Ducting	Metal	Refurb-demolition
Temple Park Leisure Centre	99 - External - 501	Sky Light	Non Asbestos	Refurb-demolition
Temple Park Leisure Centre	99 - External - 501	Cladding	Metal	Refurb-demolition
Temple Park Leisure Centre	99 - External - 501	Plant Equipment	Non Asbestos	Refurb-demolition
Temple Park Leisure Centre	99 - External - 501	Gaskets	Non Asbestos	Refurb-demolition
Temple Park Leisure Centre	99 - External - 501	Pipe Insulation	MMMF	Refurb-demolition
Temple Park Leisure Centre	99 - External - 501	Walls	Brick Block Walls	Refurb-demolition
Temple Park Leisure Centre	99 - External - 501	Door And Frame	Metal	Refurb-demolition
Temple Park Leisure Centre	99 - External - 501	Window Frame	Metal	Refurb-demolition
Temple Park Leisure Centre	99 - External - 501	Damp Proof Course	Non Asbestos	Refurb-demolition
Temple Park Leisure Centre	99 - External - 501	Chimney	Metal	Refurb-demolition

6.0 CONCLUSIONS AND ACTIONS

The enclosed report has been produced to allow the Duty Holder meet their specific instruction and generally as part of the Duty to Manage Asbestos (Regulation 4 Control of Asbestos 2006).

In accordance with the Health and Safety Executive Guidance HSG 264 Asbestos: The Survey Guide. The Client/Duty Holder should carry out the following to check the accuracy of the report:


The Client/Duty Holder should check the accuracy of this Survey Report to ensure that it meets the Client's requirements. Where ACMs have been identified, please refer to the Executive Summary and Asbestos Register. The spatial arrangement of sampling locations and occurrence of ACMs identified is depicted on the Site Plan enclosed.

Where ACMs have been identified/presumed remedial actions have been provided based upon the material assessment. Please refer to the Executive Summary. ACMs with a material assessment score of 10 or more should be regarded as high risk with a significant potential to release fibres, if disturbed. Material scores between 7 and 9 are regarded as medium risk and between 5 and 6 as low risk. Scores of 4 or less are very low risk. Non-asbestos materials are not scored. The material assessment score represents the initial assessment of the priority and control action. Remedial actions guidance based on the material score have been provided in the Executive Summary. The Client/Duty Holder should be aware of the possibility of the presence of ACMs to those areas not accessible at the time of the Survey (please refer to Executive Summary) on Outside the Scope of this Survey. The Client/Duty Holder is advised that this Survey is not the end point in managing asbestos. The Client/Duty Holder is advised that in order to comply with Regulation 3 of the "Management of Health & Safety at Work Regulations (as amended) 1999" and Regulation 6 of the "Control of Asbestos 2006" retained ACMs should be supported by a suitable and sufficient Risk Assessment. The Client/Duty Holder is advised:

- The ACMs identified should be brought to the attention of anyone likely to disturb them;
- Do not use this report exclusively in any Measurement of ACM's or Abatement Work;
- Any access/disturbance into all areas outside the scope of the Survey Report is precluded by an inspection and testing of any suspect materials.

The Client/Duty Holder should now prepare an Asbestos Register/Property Action Plan (PAP) to encompass all elements of asbestos compliance.

OHS have prepared the following Asbestos Knowledge Chain to provide transparency of the process of achieving and maintaining compliance:



OHS would be pleased to assist in all the above and ongoing compliance.


7.0 Bulk Sample Analysis

Sample No	Analysis	Other Components	Analysed By	Analysed Date	Checked By	Checked By Date
1	NAD	Organic	Nighat Yasmin	17/11/2011		17/11/2011
2	NAD	Organic	Nighat Yasmin	17/11/2011		17/11/2011
3	NAD	Organic	Nighat Yasmin	17/11/2011		17/11/2011
4	NAD	Organic	Nighat Yasmin	17/11/2011		17/11/2011
5	Chrysotile (white)		Nighat Yasmin	17/11/2011		17/11/2011
6	NAD	Organic	Nighat Yasmin	17/11/2011		17/11/2011
7	NAD	Organic	Nighat Yasmin	17/11/2011		17/11/2011
8	NAD	Organic	Nighat Yasmin	17/11/2011		17/11/2011
9	NAD	Organic	Nighat Yasmin	17/11/2011		17/11/2011
10	NAD	Organic	Nighat Yasmin	17/11/2011		17/11/2011
11	NAD	Organic	Nighat Yasmin	17/11/2011		17/11/2011
12	NAD	Organic	Nighat Yasmin	17/11/2011		17/11/2011
13	NAD	Organic	Nighat Yasmin	17/11/2011		17/11/2011
14	NAD	Organic	Nighat Yasmin	17/11/2011		17/11/2011
15	NAD	Organic	Nighat Yasmin	17/11/2011		17/11/2011
16	NAD	Organic	Nighat Yasmin	17/11/2011	Tim Brownridge	17/11/2011
17	NAD	Organic	Nighat Yasmin	17/11/2011		17/11/2011
18	Chrysotile (white)		Nighat Yasmin	17/11/2011		17/11/2011
19	NAD	Organic	Nighat Yasmin	17/11/2011		17/11/2011
20	NAD	Organic	Nighat Yasmin	17/11/2011		17/11/2011
21	NAD	Organic	Nighat Yasmin	17/11/2011		17/11/2011
22	NAD	Organic	Nighat Yasmin	17/11/2011		17/11/2011
23	NAD	Organic	Nighat Yasmin	17/11/2011		17/11/2011
24	NAD	Organic	Nighat Yasmin	17/11/2011		17/11/2011
25	Chrysotile (white)		Nighat Yasmin	17/11/2011		17/11/2011
26	NAD	Organic	Nighat Yasmin	17/11/2011		17/11/2011
27	NAD	Organic	Nighat Yasmin	17/11/2011		17/11/2011
28	NAD	Organic	Nighat Yasmin	17/11/2011		17/11/2011
30	NAD	Organic	Nighat Yasmin	17/11/2011		17/11/2011
31	NAD	Organic	Nighat Yasmin	17/11/2011		17/11/2011
32	NAD	Organic	Nighat Yasmin	17/11/2011	Tim Brownridge	17/11/2011
33	NAD	Organic	Nighat Yasmin	17/11/2011	Tim Brownridge	17/11/2011
34	NAD	Organic	Nighat Yasmin	17/11/2011		17/11/2011
35	NAD	Organic	Nighat Yasmin	17/11/2011		17/11/2011
36	NAD	Organic	Nighat Yasmin	17/11/2011		17/11/2011
37	NAD	Organic	Nighat Yasmin	17/11/2011		17/11/2011
38	NAD	Organic	Nighat Yasmin	17/11/2011		17/11/2011
39	NAD	Organic	Nighat Yasmin	17/11/2011		17/11/2011
40	NAD	Organic	Nighat Yasmin	17/11/2011		17/11/2011
41	Chrysotile (white)		Nighat Yasmin	17/11/2011		17/11/2011
42	NAD	Organic	Nighat Yasmin	17/11/2011	Tim Brownridge	17/11/2011
43	NAD	Organic	Nighat Yasmin	17/11/2011		17/11/2011

UKAS TESTING
0513

Note 1	OHS Ltd are accredited by United Kingdom Accreditation Services (UKAS) for sampling and identification of asbestos by documented in-house methods in accordance with HSG248:February 2005 using polarised light optical microscopy with dispersion staining.
Note 2	Not UKAS Accredited. Non-asbestos fibres and other materials are listed to help in the interpretation of results. However they are not included in the UKAS accreditation schedule for our laboratory.
Note 3	Where the sample was not taken by OHS Ltd the result is based upon information supplied by the client delivering the samples. In this instance OHS Ltd only guarantees the accuracy of the sample analysis.
Note 4	Opinions and interpretations expressed herein, such as the type of sample are outside the scope of UKAS accreditation.

8.0 – Site Plan



This drawing is for illustration purposes only and should not be used for detailed construction works, as the drawing is not to scale and represents layout only. The hatching on the drawing denotes positive asbestos items found during the course of the survey and potential areas where asbestos could be found as those areas were inaccessible at the time of the survey undertaken by OHS Limited.

OHS
Safe in the knowledge

Listerhills Science Park
11-17 Campus Road
Bradford
West Yorkshire
BD7 1HR

Client:

South Tyneside Council

Site Address:

Ground Floor
Temple Park Leisure Centre
John Reid Road
South Shields
NE34 9UG

Building Orientation:


Key:

Asbestos Present

Asbestos Presumed

001 Sample Location

This drawing is for illustration purposes only and should not be used for detailed construction works, as the drawing is not to scale and represents layout only. The hatching on the drawing denotes positive asbestos items found during the course of the survey and potential areas where asbestos could be found as those areas were inaccessible at the time of the survey undertaken by OHS Limited.



OHS
Safe in the knowledge

Listerhills Science Park
11-17 Campus Road
Bradford
West Yorkshire
BD7 1HR

Client:

South Tyneside Council

Site Address:

First Floor
Temple Park Leisure Centre
John Reid Road
South Shields
NE34 9UG


Building Orientation:

Key:

Asbestos Present

Asbestos Presumed

001 Sample Location



This drawing is for illustration purposes only and should not be used for detailed construction works, as the drawing is not to scale and represents layout only. The hatching on the drawing denotes positive asbestos items found during the course of the survey and potential areas where asbestos could be found as those areas were inaccessible at the time of the survey undertaken by OHS Limited.

OHS
Safe in the knowledge

Listerhills Science Park
11-17 Campus Road
Bradford
West Yorkshire
BD7 1HR

Client:

South Tyneside Council

Site Address:

Second Floor
Temple Park Leisure Centre
John Reid Road
South Shields
NE34 9UG

Building Orientation:

Key:

Asbestos Present

Asbestos Presumed

001 Sample Location

9.0 – Pre-Survey Questionnaire / Survey Scope

OHS
Safe in the knowledge

CONTRACT REVIEW & SURVEY DESK-TOP STUDY

Please complete all relevant sections of this OHS contract review and survey desk top study form to the best of your knowledge and provide the required declarations at the end of the form. Please note that a lack of premises information and/or restrictions imposed on the scope and extent of a survey can lead to survey limitations and caveats which can undermine the usefulness of the resulting survey report.

1. Client Details

Client Details	Organisation Name: South Tyneside Council	Address: Town Hall Westoe Road, South Shields Postcode: NE33 2RL
Contact Details	Name: Michael Hicks	Mobile: 07557 203 980 E-mail: Michael.hicks@southtyneside.gov.uk
Project Details	Quotation Number: BQ11-3341 Project Number (if available): **B-66870**	Date of Enquiry: 14/10/2011
Client Status	Existing Client ☐ New Client x	Information Provided by: Email x Site Visit x Telephone x Letter ☐

2. Details of Property to be Surveyed - Please submit spreadsheet containing this information where there are numerous properties

Full Address and Postcode	Site Contact & Site Contact Tel No.	Age	Approx Size (m2) / No. of Rooms	Building Classification
Temple Park Leisure Centre South Shields NE34 9UG	Ron Brown 0191 424 6404	**Pre-1985** x Pre-1999 ☐ Post-1999 ☐	ft^2 N/A	Domestic ☐ Commercial x Industrial ☐

3. Property Type

Administration ☐	Medical ☐
College / University ☐	Offices ☐
Commercial x	Food ☐
Factory ☐	Retail ☐
Hospital ☐	Shopping Centre ☐
Manufacturing ☐	Warehouse ☐

Other ☐ Specify: **Leisure Centre**

4. Operational Status

Operational x

Vacant ☐

Derelict ☐

Fire Damaged ☐

Structurally Unsound ☐

Listed / Protected ☐

Lighting / Power Available? Yes ☒ No ☐

5. Type of Survey(s) Required

Management Survey	Required
Refurbishment Survey	Required x
Demolition Survey	Required
Mixed Survey (R&D / MS)	Required

Sampling Required?	Yes x No ☐
Priority Risk Assessment Required?	Yes ☐ No x
Priority Risk Assessment By?	Survey Team ☐ Client Consultation ☐

6. Scope of Survey

Full Survey Whole property including surrounding grounds, outbuildings, and related structures.	☐
Communal areas Limited survey of property to include only public access/service areas/common areas within the building (does not include privately occupied offices/shops/flats).	☐
Partial Survey Client defined areas (please specify project areas): **Leisure Centre Communals, Kitchen, Sports Hall, Gynasium, Squash Courts, Plant Rooms etc (see plans)**	x

7. Proposed Survey Dates

Approx: From: 31st October To: 4th November

8. Proposed Report Submission Date

Date: 14 days after survey

9. Data System to be Utilised

Tracker	x
AMS / Solar	☐
MiCAD	☐
Other (please specify):	☐

10. URNs

Client Unique Space References to be used Yes x No ☐

11. Survey Plans

OHS Produced Hand-drawn Plans	☐
OHS Produced MS Visio Plans	☐
OHS Produced CAD Plans	☐
Update of Client Supplied Diagrams	x

12. Report Delivery

Hard Copy – No. of Copies Required:	x
Email:	x
CD:	☐
Online Database:	☐

13. Pre-Survey Details - Please confirm the following and, as required, indicate where the necessary information is being made available to OHS.

All Survey types

x Full site plans requested	x Received
x Unique space references requested	x Received
x Details on any special arrangements required for access to rooms and areas requested	x Received
x Details of previous surveys / abatement works requested	x Received
x Details of site history requested	☐ Received
x Information on inductions and 'permits to work' requested	x Received
x Site rules for contractors requested	☐ Received
x Risk assessment for property requested	☐ Received
x Details of maintenance schedule requested	☐ Received
x COSHH details requested	☐ Received

Refurbishment and Demolition Surveys Only

x Full scope of works for refurbishment / demolition requested	☐ Received
x Proposed plans requested	x Received
☐ Architectural information requested	☐ Received

In absence of the above information:

x Client site attendance requested for verbal scope	x Arranged

Contact Name: Michael Hicks Contact Telephone No: 07557 203 980

x Confirmation that survey areas will be unoccupied at time of inspection requested	x Received

14. Are inspections to be held in any of the following areas? Where multiple properties in programme, please detail affected properties on spreadsheet.

x Live Electrics (if isolated)	x Lift Shafts (if isolated)	x Roof Voids
x Ceilings and Ceiling Voids >4m	☐ Noise Zones	☐ Radiation Hazard Areas
☐ Biological Hazard Zones	☐ Ducts	☐ Voids / Undercrofts
☐ Operable Plant & Machinery	☐ High Level Gantries	☐ Hot Services
☐ Other Hazardous Areas (Specify:)		

15. Will the survey require any of the following? Where multiple properties in programme, please detail affected properties on spreadsheet.

x Ladders / Steps	x Tower Scaffold	x Hydraulic Platform
☐ Temporary Lighting	x Reinstatement Work	x Isolation of Services (TBC)
☐ Air Ventilation in Specific Areas	☐ Special Provision PPE	☐ Hygiene Facilities
☐ Crawl Boards	☐ Specialist Training / Clearance	x CSCS Qualified Staff
x 2nd Person in Attendance	Additional Details:	

16. Is attendance required from any of the following? Where multiple properties in programme, please detail affected properties on spreadsheet.

x The Client (Access / Security)	x Lift Engineer (if possible)	☐ Mechanical/Electrical Engineer
☐ Licensed Asbestos Contractor	☐ Builder / Reinstatement Contractor	☐ Specialist Access Contractor
☐ Confined Spaces Trained Personnel	☐ Special Provision PPE	☐ Hygiene Facilities
x 2nd Person	Additional Details:	

17. Bulk Sampling Strategy

As per HSG264 or OHS Documented Asbestos Surveying and Sampling Methodology:

- Estimated No. of Samples: 35
- Proposed No. of Samples: 35
- Explanation of difference from HSG264 (if any): None

18. Air Monitoring Strategy

Air monitoring required: **Yes** ☐ **No** x

Strategy agreed with client:

- N/A

19. Buildings / Areas to be surveyed

B66869 - Leisure Centre – (as per plans provided and scope agreed on site)

R & D Survey of Communal Areas, Sports Halls, Squash Courts, Gymnasium, Changing Areas, Plant Rooms, Canteen & Kitchen (as per report drawings).

High level access required using MEWP & Scaffold Tower.

Management survey of externals (no intrusion).

Note – Survey is based around new Mechanical, ductwork and associated service installations & replacements throughout these areas. No fixed or prestigous floors to be intruded i.e. Squash Courts & Sports Hall.

Any lift shafts or live services will only be surveyed should an engineer be present on site to isolate.

20. Site History (record previous site history if known)

- Lucion Type 2 Survey provided.

21. Agreed Survey Exclusions

- Decorative flooring (Leisure Centre)
- Lift Shaft if access not provided by engineer (Leisure Centre)
- Live services & elements

All exclusions have been agreed on site with the client **Yes** x

22. Additional Comments / Requirements

- All openings must be covered with white hardboard (painted) and fixed with no nails.

The information for the requested survey work submitted above is accurate to the best of my knowledge and I accept that any limitations not detailed above but encountered on site may result in delays to reporting and possibly additional costs being incurred should additional visits to site be required to access all required areas. This document is based on information provided by the client.

OHS Representative Declaration:

Print Name:	**Anthony Usher**
Position/Role:	**Business Development Consultant**
Date:	**27th October 2011**

Optional:

Client Declaration of Acceptance:

Print Name:	
Position/Role:	
Date:	