

A



B



C



D



E



F

Photos:

A - Front facade elevation
B - Rear and side elevation
C - Rear elevation, 1st & 2nd floors from garage forecourts
D - State of existing cement-based pointing to front facade
E - Rear elevation, ground & 1st floors
F - Rear elevation, 1st & 2nd floors



G



H



I



J



K



L

Photos:

G,H,I - Examples of damaged string courses requiring lime mortar based surface repair, ground floor, front.

J,K - Examples of upper string courses requiring lime mortar based surface repair, 1st floor, front.

L, M - Hard stone front portico door surround and door to be restored on a like-for-like basis.



M