

[illegible]

**INTERNAL PARTITIONS** – Partitions to be shown: 1/4" thick, steel, fixed other side with 12 gage thin, Soundex®-engaged, flared, and sealed at base joint. Intend 2 gage thin, fixed other flange. R-1200 to many where shown on Floor Plans. AS: timber frame manufacturers details. **NEW: DOCKING PARTITION TO SHORE OF BUILDING TO BE CONSTRUCTED AS TIMBER FRAME MANUFACTURERS DETAILS.**

Shrinkage gap must be allowed for at all window sills and at eaves / parapet levels; and appropriately sealed with suitable compression sealant (Specified by Tf. manufacturer),

GF - 5mm  
FF - 10mm  
Eaves & Parapets - 15mm

[illegible]

Rows of heat fixings omitted for clarity

length = 115mm

Roofing on slates

1 milled lead sheet (milled lead sheet being 1500mm for lining)

Saddle

Valley board (see traditional rafters)

Wall

Diagram illustrating the experimental apparatus. It shows a 4mm plywood board and a Noggin (a vertical support) positioned to hold the board in place. The board is labeled "4mm plywood" and the support is labeled "Noggin". The diagram also indicates "Board positions" with arrows pointing to the board's location.

alls, provide  
Xtratherm

8. \_\_\_\_\_

[www.abccarch.co](http://www.abccarch.co).  
[mail@abccarch.co](mailto:mail@abccarch.co).

—

၈၄

A

Rev	Revision	Date
A	Gas membrane updated, details and additional notes added, as requested by environmental Department.	20.06.2017