

1. Green roof sections are not to include any form of boundary protection or man safe

anchoring system.

2. All maintenance works are to be undertaken either via specially constructed temporary scaffolding or via another similar method to the design of the maintenance operatives.

3. Any system proposed must be suitable for purpose and comply with all relevant safety standards to ensure not risk to health or safety of maintenance operatives, general public

proposals are to be supplied to the client in advance of work being

5. All maintenance works required within the first year following practical completion (include rectification of any defects/failures) are to be included within the works package supplier/installer

6. Any ongoing maintenance works required after the initial 1 years maintenance work is to be agreed separately with the client as part of the overall building ongoing maintenance

Water reservoir to provide moisture retention element to green roof build up, specification to sedum matting supplier details

specification to sedum matting supplier details

to sedum matting supplier details

Sedum matting vegetation layer, detailed specification/species mix to be agreed, detailed proposals to be supplied by green supplier for approval prior to ordering

Waterproof membrane - for details refer to Architects/Engineers details and specification

	•								
Scale.	Dwg.		Client	Proj.	Rev.	J	Þ		С
as shown @ A3	Green Roof Area Planting Proposals	South Tyneside NHS Foundation Trust		SOUTH TYNESIDE CARE HUB		Minor amendments to account for revised building ground floor layout and BREEAM requirements Revised in accordance with approved VE items and issued for final contract issue Annotations and details updated in accordance with Architect comments			
Date.	a als			IDE CARE HUB					
15 12 14							d In accordar	for revised bu \M requiremen proved VE iten	
SOU Charte					ice with	ms and	illding		
Tel 0191 440 0034	Southerngreen chartered landscape architects			Loc.	CDM.	yes	yes	yes	yes
			NE34	Ву.	DH	LHa	LНа	LHa	
21 Durhar L				34	Chk.	RS	RS	RS	RS
am Road Low Fell					Date.	17 12 14	24.12.14	28.05.15	06.07.15

891_124

Rev.

C