© This drawing should only be used for the purpose for which it is intended. All rights are reserved and it should not be reproduced without written permission. All dimensions are to be checked on site before commencement of any work. Any discrepancies between this drawing and information issued in the accompanying report should be forwarded to this office for clarification before proceeding.

The original of this drawing was produced in colour, a monochrome copy should not be relied upon.

Key:

- T1 — Tree Number
- Trees To Be Removed Broken Black Ring Surrounding Crater
- Tree Quality Assessment Crater Colours As Below
- Green Crater = High Quality (Denoted By Letter A)
- Blue Crater = Moderate Quality (Denoted By Letter B)
- Yellow Crater = Low Quality (Denoted By Letter C)
- Red Crater = Unsuitable To Retain (Denoted By Letter U)

Institute of Chartered Foresters
Registered Consultant

Arboricultural Impact Assessment
Tree Protection Plan (TPP)

Retained Trees Shown On Proposed Layout With Protective Measures Indicated

Station Road, Hebburn

For

Projekt Architects

AllAboutTrees Ltd
Arboricultural & Ecological Consulting
Chartered Arboriculturalists & Environmentalists
The Old School, Quarry Lane,
Butterknowle, Co. Durham, DL13 5LN
Tel 0191 3739494 01388 129200
email info@allaboutrees.co.uk www.allaboutrees.co.uk

Drawn at Durham Office By TA Checked by AW

Scale 1:200 at A0 | Date 14.07.15

Registered Chartered Arboricultural Consultants
Planning & Development
Urban Forestry
Ecological Consultants

Drawing Ref: TPP | Revision: -