

## Falling Head Test Results



**Client:** Burney Midlands Ltd

**Site:** Arc Car Wash, Towers Place,  
South Shields

**Job No:** BG2578

**Date:** 2nd September 2015

### BOREHOLE 1

**Depth Water Added from** 3.0m

**Depth Water Added from**

**Depth Water Added to** 1.5m

**Depth water added to**

Time	Depth of water drop	Time	Depth
0945hrs	Water added		
0946hrs	No drop		
0947hrs	No drop		
0948hrs	No drop		
0949hrs	No drop		
0950hrs	No drop		
0955hrs	No drop		
1000hrs	No drop		
1015hrs	No drop		
1030hrs	No drop		
1045hrs	No drop		
1115hrs	No drop		
1145hrs	No drop		
1215hrs	No drop		
1230hrs	No drop		
1245hrs	No drop		
No water drop in 3 hours.			