


Knock - Two, Fir Door Combination

Alumina Window
Affected By Downfall



Moist GUTTER ALUMINA COATED, ALUM DOWNFALL
EXT. SET OUT POINT AT CORNER

Contract Ref No:- R 25935

Mrs + Mrs. KANAKES
11D CAMBRIDGE AVENUE
HEBBOLD
TAMIL NADU
NE:31 201

Tel: 0191 4206242

Customer Signature of Approval: _____

SCALE 1:50

9.6.2016

S. Muskan

peminine
HOME IMPROVEMENTS

for a better home tomorrow
take the peminine way today