

2b


THE BARNES INSTITUTE SR6 7BY PHASE 1 WINDOW REPLACEMENT

Barnes Institute

F. F. bay sliding sash centre and end frame elevations

Detail in black showing existing box sash lining.

Detail in brown showing new sliding sashes and glass sizes.



2b An integrated two-storey 3-frame bay window on the first floor;
1 centre frame and 2 side frames, 1 left and 1 right;