

3

THE BARNES INSTITUTE SR6 7BY PHASE 1 WINDOW REPLACEMENT

Barnes Institute


F. F. Front sliding sash office and store elevations.

Detail in black showing existing box sash lining.

Detail in brown showing new sliding sashes and glass sizes.



Office



Store

Scale 1:20

3. Two windows on the first floor above the shop display windows;