

5

THE BARNES INSTITUTE SR6 7BY PHASE 2 WINDOW REPLACEMENT

Barnes Institute


G. F. Side sliding sash elevations.

Detail in black showing existing box sash lining.

Detail in brown showing new sliding sashes and glass sizes.



3 large (5a)



4 small (5b)

Scale 1:20

5. Seven blocked-up ground floor windows to be replaced on the south face of the building, 3 large (5a), 5 small (5b).